

MARINE CORPS AIR STATION
LONG RANGE
AIR FIELD MAINTENANCE PLAN

FY 1976 - 1981 *A. KEITZ*

I. Narrative:

The presentation of this plan is in response to those directives and procedures specified in MCO P11000.7A and MCO 11130.1.

Marine Corps Air Station (Helicopter), New River is located three miles south of the City of Jacksonville at an elevation of twenty-four feet above sea level. There are two major runways, each 5200 feet long by 150 feet wide, emanating from a common hub. The present facilities began with the original construction beginning in 1942 and developed through modification, addition, extension, and strengthening of the pavement to the present. A reduced scale plan of the airfield is provided in Tab A.

A pavement evaluation was performed during January and February 1976 by LANTNAVFACENGCOCM as per our request. The results of this survey were published in May 1976 authored by E. H. INBY of LANTNAVFACENGCOCM. This survey presents specific data on the pavement conditions and the recommended wheel loading for various areas using aircraft C130 and C141 as examples. A portion of this survey is provided in Tab B.

Marine Corps Air Station (Helicopter), New River maintains twenty-four hour all-weather air operational facilities supporting the 2d Marine Aircraft Wing. Data reflecting airfield operations are provided in Tab C.

The presentation of this plan is in response to those directives

and procedures specified in WFO 81100.7A and WFO 1113.1.

Marine Corps Air Station (Helicopter), New River is located three miles south of the City of Jacksonville at an elevation of twenty-four feet above sea level. There are two major runways, each 5200 feet long by 150 feet wide, emanating from a common point. The present facilities

began with the original construction beginning in 1942 and developed through modification, addition, extension, and strengthening of the pavement to the present. A reduced scale plan of the airfield is provided in Tab. A.

A pavement evaluation was performed during January and February 1976 by LANTVAVACENGCOM as per our request. The results of this survey were published in May 1976 authored by E. H. LIMBY of LANTVAVACENGCOM. This

survey presents specific data on the present conditions and the recommended wheel loading for various areas using aircraft C130 and C141 as examples. A portion of this survey is provided in Tab. B.

Marine Corps Air Station (Helicopter), New River maintains twenty-four hour all-weather air operational facilities supporting the 2d Marine Aircraft Wing. Data reflecting airfield operations are provided in Tab. C.

Repair and Replacement History

The first repair project of any scope, after original construction, was Contract NOY 83267, 1954. All runways and taxiways were resurfaced at this time. The runways received only patching and minor repairs until complete resurfacing of runway 5-23 and slurry treatment of 18-36 in 1975. The present parking aprons were constructed by increments from 1954 to the present. The lighting system cable was replaced in 1965; however, the lighting fixtures were not replaced. Tab D provides data reflecting the growth of the airfield and the most recent repairs.

Maintenance of Airfield

The current planning for maintenance and repair is reflected in the anticipated repair projects and the known required maintenance, Tab E. Preventive Maintenance inspections of airfield lighting are being performed and have contributed to the decrease in the number of lighting failures.

Tab Index

- Tab A Scale Plan of Airfield
- Tab B Airfield Pavement Evaluation
- Tab C Airfield Operation/Usage
- Tab D Airfield Growth/Recent Repairs
- Tab E Airfield Long Range Maintenance Plan

The first repair project of any scope, after original construction, was Contract NOY 33237, 1954. All runways and taxiways were resurfaced in this year. The runways received only patching and minor repairs until complete resurfacing of runway 5-23 and slurry treatment of 18-36 in 1975. The present parking aprons were constructed by increments from 1954 to the present. The lighting system cable was replaced in 1955; however, the lighting fixtures were not replaced. Tab D provides data reflecting the growth of the airfield and the most recent repairs.

Maintenance of Airfield

The ongoing planning for maintenance and repairs is reflected in the scheduled repair projects and the known required maintenance, Tab E. Preventive maintenance inspections of airfield lights are being performed and have contributed to the decrease in the number of lighting failures.

Tab Index

Tab A	Scale Plan of Airfield
Tab B	Airfield Pavement Evaluation
Tab C	Airfield Operation/Usage
Tab D	Airfield Growth/Recent Repairs
Tab E	Airfield Long Range Maintenance Plan

TAB PLACEMENT HERE


DESCRIPTION:


Tab A

Tab page did not contain hand written information

Tab page contained hand written information
*Scanned as next image

T
A
B
A





- LEGEND**
- PLATE LOAD TESTS, ASPHALTIC CONCRETE PAVEMENT.
 - 6" DIAMETER CORE CUT, PORTLAND CEMENT CONCRETE PAVEMENT.

ATLANTIC DIVISION	
NAVAL STATION	
MCAS DJ NEW RIVER JACKSONVILLE, N. C. TEST LOCATION MAP	
NO. 80091	DATE 1954
BY	APP. 10



TAB PLACEMENT HERE


DESCRIPTION:

Tab B

Tab page did not contain hand written information

Tab page contained hand written information
*Scanned as next image

T
A
B
B





DEPARTMENT OF THE NAVY
 ATLANTIC DIVISION
 NAVAL FACILITIES ENGINEERING COMMAND
 NORFOLK, VIRGINIA 23511

TELEPHONE NO.
 444-7631
 AUTOVON 690-7631
 IN REPLY REFER TO:
 411:TPM
 11132/CHERPT
18 JAN 1974


To: Commander, Marine Corps Air Bases, Eastern Area
 Subj: Airfield Pavement Evaluation Program
 Encl: (1) NAVFACENGCOM msg 071934 Jan 1974

1. In order to provide the information requested by enclosure (1), the Marine Corps Air Station's requirements can be best ascertained at your command. It is therefore requested that you provide us with your needs by 23 January 1974 if possible. Your requirements should be designated as to type of program (i.e., condition survey, pavement evaluation or skid-resistance measurements) or any combination of type, as well as, the specific runways, taxiways or parking aprons to be included.
2. Since the schedule of work for FY75 will ultimately be established by NAVFACENGCOM, your justification of need will be submitted in the same form that we receive it.
3. As you know, the purpose of the program is to help you determine the type of maintenance required for aircraft pavements and the priority of need in order to use the limited maintenance funds to your best advantage.
4. If questions arise concerning this program, please contact Tom McAndrews, LANTNAVFACENGCOM on AUTOVON 690-7631.

J. F. Norton
 J. F. NORTON
 BY DIRECTION

Copy to:
 NAVFACENGCOM

22 Jan 74
 G-4 ROUTING SLIP
 ACOFB G-4 _____
 ASST G-4 _____
 LOG OFF _____
 LOG CHIEF *off* _____
 EMBR AFFAIRS _____
 AEOO _____
 DEPUTY AEOO _____
 SPTT REG O _____



USE FOR URGENT
LETTERS ONLYCLEAR T.
COMMUNICATIONS

CHECK TYPE OF MAIL <input checked="" type="checkbox"/> AIR <input type="checkbox"/> REGISTERED <input type="checkbox"/> CERTIFIED <input type="checkbox"/> SPECIAL DELIVERY	CLASSIFICATION UNCLASSIFIED	INSTRUCTIONS 1. Message type phrasenology is permissible. 2. Both addresses must be appropriate for window envelope or bulk mailing, as intended. Include attention codes, when known. Use dots and brackets as guides for window envelope addresses. 3. Give priority to processing, routing, and action required. Avoid time-consuming controls. 4. In order to speed processing, a readily identifiable, special window envelope, OPNAV 5215/145A, Speedletter Envelope, is provided for unclassified speedletters where bulk mailing is not used. Other window envelopes also may be used. In bulk mail, speedletters should be placed on top of regular correspondence.
	DATE 11 Mar 1975	
To: Commanding Officer Naval Facilities Engineering Command Alexandria, Virginia 22332 a: (1) Commanding Officer, LANTRDIVNAVFACENGCN, Norfolk, VA 23511 (2) Commanding Officer, SOUTHDIVNAVFACENGCN, Charleston, South Carolina 29402		

Fold STANDARD REFERENCES AND ENCLOSURES, IF ANY; TEXT AND SIGNATURE BLOCK

Subj: **Airfield Pavement Evaluation Program**Ref: (a) **NAVFACINST 11132-143**1. Reference (a) gives background and program requirements of the **Airfield Pavement Evaluation Program.**

2. In accordance with reference (a), the following surveys and evaluations are requested for Marine Corps Bases East:

a. **MCAS Cherry Point**

- (1) Runway friction measurement survey;
- (2) Airfield pavement condition survey.

b. **MCAS (H) New River**


- (1) Runway friction measurement survey;
- (2) Airfield pavement condition survey.

COPY TO

← ADDRESS
 REPLY AS SHOWN AT LEFT;
 OR, REPLY HEREON AND
 RETURN

CLASSIFICATION

B-3



Naval Speedletter

USE FOR URGENT
LETTERS ONLY

DO NOT CLEAN
COMMUNICATIONS

CHECK TYPE OF MAIL: <input checked="" type="checkbox"/> REGULAR <input type="checkbox"/> REGISTERED <input type="checkbox"/> AIR <input type="checkbox"/> CERTIFIED <input type="checkbox"/> SPECIAL DELIVERY	CLASSIFICATION		INSTRUCTIONS 1. Message type phraseology is permissible. 2. Both addresses must be appropriate for window envelope or bulk mailing, as intended. Include attention codes, when known. Use dots and brackets as guides for window envelope addresses. 3. Give priority to processing, routing, and action required. Avoid time-consuming controls. 4. In order to speed processing, a readily identifiable, special window envelope, OPNAV 5214/115A, Speedletter Envelope, is provided for unclassified speedletters where bulk mailing is not used. Other window envelopes also may be used. In bulk mail, speedletters should be placed on top of regular correspondence.
	DATE	IN REPLY REFER TO	

To:

Fold STANDARD REFERENCES AND ENCLOSURES, IF ANY; TEXT AND SIGNATURE BLOCK

c. MCAS Beaufort

- (1) Airfield pavement evaluation of East/West tow way to full power run-up area;
- (2) Airfield pavement condition survey.

B. A. MAS
By direction

Fold

COPY TO


From:

Commander
Marine Corps Air Bases, Eastern Area
Cherry Point, North Carolina 28533

← ADDRESS
REPLY AS SHOWN AT LEFT;
OR, REPLY HEREON AND
RETURN

CLASSIFICATION

B-4





DEPARTMENT OF THE NAVY
ATLANTIC DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
NORFOLK, VIRGINIA 23511

TELEPHONE NO.

444-7631

AUTOVON 690-7631

IN REPLY REFER TO:

411:TPM

11132/CHERT

24 MAR 1975

FIRST ENDORSEMENT on COMCABEAST spltr LF-md/FES of 11 Mar 1975

From: Commander, Atlantic Division, Naval Facilities Engineering
Command

To: Commander, Naval Facilities Engineering Command


Via: Commanding Officer, Southern Division, Naval Facilities
Engineering Command

Subj: Airfield Pavement Evaluation Program

1. This office concurs with request contained in paragraph 2 of basic correspondence.

J. M. DAVIS
BY DIRECTION

Copy to:
✓ COMCABEAST





DEPARTMENT OF THE NAVY
ATLANTIC DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
NORFOLK, VIRGINIA 23511

TELEPHONE NO.
444-7631
AUTOVON 690-7631
IN REPLY REFER TO:
411:TPMcA
7 May 1976

From: Commander, Atlantic Division, Naval Facilities Engineering Command
To: Commanding General, Marine Corps Base, Camp Lejeune, North Carolina

Subj: Aircraft Pavement Evaluation, Marine Corps Air Station (Helicopter),
New River

Ref: (a) MARCORB CAMLEJ ESR dated 5 Nov 1975

Encl: (1) Airfield Pavement Evaluation, MCAS (Helicopter) New River


1. The requested field investigation and report, enclosure (1), has been completed and is submitted in response to reference (a).

E. H. IRBY
BY DIRECTION

Copy to:
PWO CAMLEJ

→ Base Maintenance Officer CAMLEJ
Attn: Lt. Davis
CO NEW RIVER
Air Operations Officer NEW RIVER
Airfield Facilities Officer NEW RIVER
Attn: Maj. Morgan





GENERAL INFORMATION

At the request of the Commanding Officer, Marine Corps Air Station (Helicopter) New River, a pavement evaluation consisting of plate bearing tests and concrete core testing was performed on all airfield pavements during the months of January and February 1976. The purpose of the evaluation was to update the allowable gross aircraft load capability of the runways, taxiways and parking aprons for fixed wing, cargo aircraft type traffic. Although ninety percent of the aircraft utilizing this airfield are helicopters, there are occasions during military exercises when large cargo type aircraft use the field. The majority of these cargo planes are C-130's with a small percent being C-141's.

The allowable gross aircraft load chart accompanying this report contains information for the specific cargo aircraft which uses this field on occasion, as well as the standard single and dual wheel geared aircraft with 150 psi tire pressure. This was done at the request of the air operations officer to facilitate their decision making.

CONCLUSIONS AND RECOMMENDATIONS

Since information provided by station personnel indicated that C-130 aircraft operated at New River with tire pressures of 100 psi and C-141 operated at 170 psi, the following conclusions and recommendations assumed these conditions as normal and are based on this data.



1. Runway 18-36 is in very good condition and is capable of accommodating fully loaded C-130 aircraft. C-141 type aircraft should be restricted to approximately a 185,000 pound gross load with 170 psi tire pressure. The allowable gross increases to 216,000 pounds if the tire pressure is reduced to 150 psi.

2. Runway 5-23 is in excellent condition. Part of this runway was reconstructed in 1975 when the entire runway was overlaid with 1-1/2" of asphaltic concrete. A fully loaded C-130 can safely operate from this runway but a C-141 aircraft should be restricted to approximately 152,000 pounds of gross load when tire pressure is 170 psi. This limitation is due to the weak area between Stations 38+00 and 43+00. This gross load can be increased to 179,000 pounds if the tire pressure is reduced to 150 psi.

3. Taxiway "A" will support C-130 aircraft but should be restricted to C-141 type aircraft with maximum loads of 164,000 pounds if the tire pressure is reduced to 150 psi.

4. Taxiway "B" is the newest and the weakest of the airfield pavements. This taxiway was reconstructed the latter part of 1975. During our investigation it was determined that water had become trapped in the basecourse and subgrade. Due to the impervious subgrade material it is impossible for the water to drain either longitudinally or transverse resulting in a weak basecourse and subgrade and in a low allowable gross aircraft load rating. Nothing but light weight aircraft should be allowed



on this taxiway, as long as this soft and wet condition exists.


5. The flexible portions of Taxiways "C", "E" and "F" are in excellent condition and are capable of supporting fully loaded C-130 and C-141 type aircraft if the tire pressure is reduced to 150 psi.

6. The portion of Taxiway "D" west of Runway 18-36 can support a C-130 fully loaded allowing an overload of less than 10%. This overload is insignificant when the frequency of this type traffic is considered. A C-141 should not use this taxiway unless its gross weight is less than 127,000 pounds. This gross weight can be increased to 146,000 pounds if the tire pressure is reduced to 150 psi.

7. That portion of Taxiway "D" east of Runway 18-36 and including the Compass Rose showed a greater strength than the west side previously described (except for the shoulder pavement). There is no overload condition using a fully loaded C-130 and a C-141 should be limited to 230,000 pounds gross weight. With tire pressure reduced to 150 psi, the gross load can be increased to 263,000 pounds.


8. The ten inch rigid pavement adjacent to Hanger 504 will support a fully loaded C-130 or C-141.

9. The majority of the mat areas are constructed with six inches of portland cement concrete. This pavement is of excellent quality as is the basecourse. The load restriction of this pavement is due to the thickness of the concrete and not any deficiencies of the existing pavement section. (See the Allowable Gross Aircraft Load Chart.)




10. Mat One Parking Apron is comparable but somewhat less in strength than the ten inch pavement adjacent to Hanger 504.

11. It should be noted that all pavement can be overloaded occasionally by as much as twenty-five percent without experiencing any immediate failures. The normal operating tire pressure of the C-141 (170 psi) is one adjustable factor that is keeping the C-141 allowable load so low. Therefore, under the C-141 heading on the Allowable Gross Aircraft Load Chart, the allowable load for tire pressures at 150 psi is shown in parenthesis.




MCAS (H) NEW RIVER
JACKSONVILLE, N.C.

PAVEMENT DESIGNATION		SURFACE		BASE		SUBBASE		SUB-GRADE	ALLOWABLE GROSS AIRCRAFT LOAD (LBS.) FOR AIRCRAFT TYPE:			
LOCATION	PAVE. LEGEND *1	TYPE	THICK. (IN.)	TYPE	THICK. (IN.)	TYPE	THICK. (IN.)	TYPE	SWG T.P. NGT 150 P.S.I.	DWG T.P. NGT 150 P.S.I.	C-130 T.P. NGT 100 P.S.I.	C-141 T.P. NGT 170 P.S.I.
UNWAY 18-36	1	A.C. Sand Asph. Sand Tar	1½" 3"-8" 3"	Shell Rock	6"	-	-	SP	111,000	144,000	O.K. Fully Loaded	185,000 (216,000 @ 150 psi)
UNWAY 5-23	2	A.C. Sand Asph. Sand Tar	3" 3"-8" 3"	Shell Rock	6"	-	-	SP	92,000	120,000	O.K. Fully Loaded	152,000 (179,000 @ 150 psi)
AXIWAY "A"	3	A.C. Sand Asph. Sand Tar	1½" 3"-8" 3"	Shell Rock	6"	-	-	SP	84,000	109,000	O.K. Fully Loaded	138,000 (164,000 @150 psi)
AXIWAY "B"	4	A.C.	4"	Black Base	6"-8"	Shell Rock	6"	CL/ML	38,000	49,000	93,000	57,000
AXIWAY "C" "E" "F"	5	A.C.	4"	Shell Rock	6"	-	-	SP	160,000	208,000	O.K. Fully Loaded	277,000 (312,000 @ 150 psi)
AXIWAY "D" (West of R/W 18-36)	6	A.C. Sand Asph. Sand Tar	4½" 3"-8" 3"	Shell Rock	6"	-	-	SP	75,000	98,000	162,000	127,000 (146,000 @ 150 psi)



REV.	DESCRIPTION	DATE	BY




LEGEND

- PLATE LOAD TESTS, ASPHALTIC CONCRETE PAVEMENT.
- 6" DIAMETER CORE CUT, PORTLAND CEMENT CONCRETE PAVEMENT.




DEPARTMENT OF THE NAVY		NAVAL FACILITIES ENGINEERING COMMAND	
ATLANTIC DIVISION			
NAVAL STATION		PORTFOLK, VA.	
MCAS (H) NEW RIVER JACKSONVILLE, N. C. TEST LOCATION MAP			
NO.	DATE	SCALE	
F	80091	1:10,000	
DATE	BY	APP'D.	BY



MCAS (H) NEW RIVER
 JACKSONVILLE, N.C.
 TENSILE SPLITTING STRENGTH


<u>MAT NO.</u>	<u>LOC. NO.</u>	<u>AVERAGE THICKNESS</u>	<u>TENSILE SPLITTING STRENGTH</u>
1	38	6"	531
	39	6"	531
			AVERAGE = 531
2	29	6"	603
	30	6"	371
			AVERAGE = 487
2	32	10"	555
	33	10"	503
	34	10"	572
			AVERAGE = 543
3	20	6"	714
	21	6"	651
	22	6"	531
	23	6"	505
	24	6"	477
	25	6"	684
	26	6"	481
	27	6"	408
28	6"	416	
			AVERAGE = 541
5	35	10"	513
	36	10"	518
	37	10"	507
			AVERAGE = 513



MCAS (H) NEW RIVER
 JACKSONVILLE, N.C.
 TENSILE SPLITTING STRENGTH

<u>MAT. NO.</u>	<u>LOC. NO.</u>	<u>AVERAGE THICKNESS</u>	<u>TENSILE SPLITTING STRENGTH</u>
6	8	6"	540
	9	6"	473
	10	6"	674
	11	6"	592
	12	6"	470
	13	6"	511
	14	6"	249 *
	15	6"	432
	16	6"	467
	17	6"	681
	18	6"	619
	19	6"	594
			AVERAGE = 550
7	1	6"	394
	2	6"	180 *
	3	6"	472
	4	6"	679
	5	6"	576
	6	6"	477
	7	6"	568
			AVERAGE = 528

NOTE: * INDICATES DELETION FROM AVERAGE.




MCAS (H) RIVER
JACKSONVILLE, N.E.

PAVEMENT DESIGNATION		SURFACE		BASE		SUBBASE		SUB-GRADE	ALLOWABLE GROSS AIRCRAFT LOAD (LBS.) FOR AIRCRAFT TYPE:			
LOCATION	PAVE. LEGEND *1	TYPE	THICK. (IN.)	TYPE	THICK. (IN.)	TYPE	THICK. (IN.)	TYPE	SWG T.P. NGT 150 P.S.I.	DWG T.P. NGT 150 P.S.I.	C-130 T.P. NGT 100 P.S.I.	C-141 T.P. NGT 170 P.S.I.
Compass Rose & Taxiway "D" (E. of R/W 18-36)	6	A.C. Sand Asph. Sand Tar	4½" 3"-8" 3"	Shell Rock	6"	-	-	SP	126,000	164,000	O.K. Fully Loaded	230,000 (263,000 @ 150 psi)
AT ADJACENT HANGAR 504	8	A.C.	1½"	Shell Rock	6"	-	-	SM	110,000	200,000	O.K. Fully Loaded	O.K. Fully Loaded
	9	P.C.C.	10"	Shell Rock	6"	-	-	SM	110,000	200,000	O.K. Fully Loaded	O.K. Fully Loaded
ATS 2 thru 7	10 thru 17	P.C.C.	6"	Shell Rock	6" to 12"	-	-	SM/SP	45,000	75,000	130,000	200,000
AT 1	18	P.C.C. A.C. P.C.C.	6" 4"-6" 6"	Shell Rock	6"	-	-	SM	80,000	145,000	O.K. Fully Loaded	O.K. Fully Loaded

* - See "Construction History Map".

SWG = Single Wheel Gear
 DWG = Dual Wheel Gear
 T.P. = Tire Pressure
 A.C. = Asphaltic Concrete
 P.C.C. = Portland Cement Concrete
 N.G.T. = No Greater Than

NOTES: Base modulus K = 500 p.c.i.
 Working Flexural Stress of P.C.C. = 500 P.S.I.
 C-130 = maximum gross load of 177,000 pounds
 C-141 = maximum gross load of 316,000 pounds



TAB PLACEMENT HERE


DESCRIPTION:

Tab C

Tab page did not contain hand written information

Tab page contained hand written information
*Scanned as next image

T
A
B
C



AIRFIELD USAGE

REPORTING PERIOD

AVERAGE MONTHLY OPERATIONS


1971	9,360
1972	9,536
1973	13,227
1974	11,384
1975	<u>9,299</u>
5 YEAR AVERAGE	10,561

HIGH MONTHLY OPERATIONS

1971	Aug. 11,778
1972	Mar. 15,057
1973	Apr. 16,918
1974	June 16,796
1975	June 13,550

AVERAGE ANNUAL OPERATIONS 126,738

TYPES OF AIRCRAFT USING THE STATION INCLUDE CH46, CH53, OV10, AH1, C117, T28, T34, C130, C141 and assorted FIXED WINGED AIRCRAFT AND HELICOPTERS.



TAB PLACEMENT HERE


DESCRIPTION:

Tab D


Tab page did not contain hand written information

Tab page contained hand written information
*Scanned as next image

T
A
B
D




TAXIWAY "B"
RESURFACED
2 JAN 1976




TAXIWAY 1
RESERVED
2 JAN 1971

TAXIWAY 1

ROCKWELL 2-234
12-21 RESERVE
3 SEP 1971






PROJECT R2-72
 RESEAL JOINTS &
 REPAIR SPALLED
 AREAS
 SHOULD BE FUNDED
 FY 77



GEOGRAPHIC LOCATION
 LONG: 77° 26' 33" W
 LAT: 34° 42' 35" N

GLITCH ANGLE
 3 TO 1
 3618

PROJECT 1077
R. E. L. LANE
NEWARK STATION
BRASS
SHEET OF PAPER
117



DATA CHART		
CODE	DESCRIPTION	CONTR. NO. & YEAR
* 1	ACCESS APRON TO HANGAR 504	NBY 70703 (1952)
** 2	A/C PARKING APRONS	NBY 51334 (1956)
** 3	A/C PARKING APRONS	NBY 15581 (1959)
4	ACCESS APRON TO HANGAR 515	NBY 40134 (1962)
5	A/C PARKING APRON	NBY 46518 (1962)
6	A/C PARKING APRON	NBY 50211 (1963)
7	A/C PARKING APRON	NBY 54138 (1963)
8	A/C PARKING APRON	NBY 60397 (1964)
9	A/C PARKING APRON	NBY 50320 (1964)
10	ACCESS APRON TO HANGAR 518	NBY 69474 (1966)
11	A/C WASHRACK	NBY 79194 (1966)
12	A/C PARKING APRON	N62470-67-B-0998 (1967)
13	ACCESS APRONS TO HANGARS 4106 & 4108 DIRECT REFUELER STA.	NBY 58179 (1967)
14	A/C PARKING APRONS & WASHRACKS	N62470-68-B-0002 (1968)
15	DIRECT REFUELER STATION	N62470-69-B-0721 (1969)
16	ACCESS APRON TO HANGAR 4100	N62470-72-B-1141 (1972)
* 1	JET FUEL RESISTANT ASPHALT OVERLAY	N62470-67-B-0500 (1967)
** 2 3	JOINTS RESEAL	N62470-67-B-0500 (1967)



LEGEND

- CONCRETE APRONS
- ▨ ASPHALT TAXIWAYS
- ▩ STRUCTURES

PLAN
SCALE: 1" = 300'

AIRCRAFT PARKING APRONS




2

C

C

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39



MAP OF
 AIR STATION AREA
 NEW RIVER
 CAMP LEJEUNE, NORTH CAROLINA
 SHOWING CONDITIONS ON
 1 OCTOBER 1974

R. Blaggett
 CAPTAIN (EC) U.S.N.
 PUBLIC WORKS OFFICER
 MCB GLNC

LAND AREA GOVT. OWNED ± 2772 AC.



FOR OFFICIAL USE ONLY

SHEET 23 OF 24



2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39

C

C

C


1



- LEGEND**
- STATION BOUNDARY LINE
 - SHORE LINE
 - RIVER FLOW
 - MAIN STATION ENTRANCE
 - EXISTING ROAD
 - EXISTING FENCE
 - RUNWAY APPROACH ZONE B CLEARANCE LINE
 - EXISTING PAVED AREA

NUMBER	USE
12	PAINT/OIL STOREHOUSE
92	NONPOTABLE WATER WELL
99	" " " "

LAND AREA: GOVERNMENT OWNED 976.5 ACRES



MAP OF
 OAK GROVE AIRFIELD
 CAMP LEJUNE, NORTH CAROLINA
 SHOWING CONDITIONS ON
 1 OCTOBER 1974

R. Daggott
 CAPTAIN (E.C.) USAF
 PUBLIC WORKS OFFICER
 AFB CLIC



TAB PLACEMENT HERE


DESCRIPTION:

Tab E

Tab page did not contain hand written information

Tab page contained hand written information
*Scanned as next image

T
A
B
E



MCAS-H AIRFIELD LONG RANGE MAINTENANCE PLAN

			1977	1978	1979	1980	1981
RUNWAYS	X	RESURFACE Located at Oak Grove		390.0			
TAXIWAYS		SEAL-COAT					
APRONS		PATCH					
OTHER		OTHER					
RUNWAYS		RESURFACE					
TAXIWAYS		SEAL-COAT					
APRONS	X	PATCH Spalled Areas					
OTHERS		OTHER Seal Expansion Joints of Areas 1 thru 5	334.0				
RUNWAYS	X	RESURFACE					
TAXIWAYS		SEAL-COAT 5-23 and 18-36			30.0		
APRONS		PATCH					
OTHER		OTHER					

MCAS-H AIRFIELD LONG RANGE MAINTENANCE PLAN

			1977	1978	1979	1980	1981
RUNWAYS	X	RESURFACE					
TAXIWAYS	X						
APRONS		SEAL-COAT					
GROUNDS		PATCH					
OTHER		OTHER Lighting Systems Maint.	7749	8678	9719	10880	12180
RUNWAYS		RESURFACE					
TAXIWAYS							
APRONS	X	SEAL-COAT					
GROUNDS		PATCH					
OTHERS		OTHER Sweep Weekly	18595	20826	23325	26124	29258
RUNWAYS	X	RESURFACE					
TAXIWAYS	X						
APRONS	X	SEAL-COAT					
GROUNDS		PATCH					
OTHER		OTHER Maintain Traffic Markings	446	499	558	624	698

Πατριάρχης Κωνσταντινουπόλεως

282 254 226 208 180

X

X

X

Πατριάρχης Κωνσταντινουπόλεως

282 254 226 208 180

X

Πατριάρχης Κωνσταντινουπόλεως

282 254 226 208 180

X

X

MCAS-H AIRFIELD LONG RANGE MAINTENANCE PLAN

				1977	1978	1979	1980	1981
RUNWAYS	X	RESURFACE						
TAXIWAYS	X							
APRONS	X	SEAL-COAT						
GROUNDS		PATCH						
OTHER		Treat Soil Around Lights and Markers with Sterilent	632	707	791	885	991	
RUNWAYS		RESURFACE						
TAXIWAYS								
APRONS		SEAL-COAT						
GROUNDS	X	PATCH						
OTHERS		Cut Airfield Grass	6600	7392	8279	9272	10380	
RUNWAYS		RESURFACE						
TAXIWAYS								
APRONS		SEAL-COAT						
GROUNDS	X	PATCH						
OTHER		Fertilize and Lime Airfield Grass			5600			

REPORTS AND TIME SHEETS, 1930

1930 1931 1932 1933 1934

REPORTS AND TIME SHEETS, 1930

1930 1931 1932 1933 1934

MCAS-H AIRFIELD LONG RANGE MAINTENANCE PLAN

		1977 1978 1979 1980 1981				
RUNWAYS		RESURFACE				
TAXIWAYS	x	SEAL-COAT				
APRONS		PATCH				
GROUNDS		OTHER	Taxiway B - Request submitted to Public Works Dept for project to relieve water intrusion under taxiway.			
OTHER						
RUNWAYS		RESURFACE				
TAXIWAYS		SEAL-COAT				
APRONS		PATCH				
GROUNDS		OTHER				
OTHERS						
RUNWAYS		RESURFACE				
TAXIWAYS		SEAL-COAT				
APRONS		PATCH				
GROUNDS		OTHER				
OTHER						

Handwritten text, possibly bleed-through from the reverse side of the page. The text is mirrored and difficult to decipher but appears to contain several lines of characters.

X

MCAS-H AIRFIELD LONG RANGE MAINTENANCE PLAN

		1977	1978	1979	1980	1981
RUNWAYS						
TAXIWAYS						
APRONS						
GROUNDS						
OTHER						
RUNWAYS						
TAXIWAYS						
APRONS						
GROUNDS						
OTHERS						
RUNWAYS						
TAXIWAYS						
APRONS						
GROUNDS						
OTHER						



MILITARY CONSTRUCTION LINE ITEM DATA		3. DEPARTMENT NAVY	4. INSTALLATION MARINE CORPS AIR STATION, NEW RIVER
6. PRIOR AUTHORIZATION P.L. 0	7. CATEGORY CODE NUMBER 111-11 112-11	8. PROGRAM ELEMENT NUMBER ----	9. STATE/COUNTRY JACKSONVILLE, NORTH CAROLINA
11. BUDGET ACCOUNT NUMBER ----	12. LINE ITEM NUMBER R4-68	13. LINE ITEM TITLE RESURFACE R/W AND T/W AT MCOLF, OAK GROVE	

SECTION A - DESCRIPTION OF LINE ITEM				SECTION B - COST ESTIMATES				
PHYSICAL CHARACTERISTICS OF PRIMARY FACILITY				20. PRIMARY FACILITY	U/M	QUANTITY	UNIT COST	COST (\$000)
a. NO. OF BLDGS. 0	b. NO. OF STORIES 0	c. LENGTH IRREG	d. WIDTH IRREG	a. Pavement Repairs	SY	(232,778)	1.38	(322)
e. SIGN CAPACITY NA	f. GROSS AREA 232,778 SY	g. COST (\$ NA)		b.		()		()
DESCRIPTION OF WORK TO BE DONE The work consists of miscellaneous patching and complete surface overlay with bituminous concrete. Airfield pavement markings will be replaced.				c.		()		()
				d.		()		()
				21. SUPPORTING FACILITIES				\$
				a.				()
				b.				()
				c.				()
				d.				()
				e.				()
				f.				()
				g.				()
				h.				()
				i.				()
				j.				()
				22. TOTAL LINE ITEM COST				\$ 322

SECTION C - BASIS OF REQUIREMENT			25. REQUIREMENT FOR LINE ITEM
E YARDS)			The airfield pavement at MCOLF, Oak Grove is of bituminous concrete placed in 1942. There have been no major repairs to date. The surface is badly cracked with many of the cracks 1 inch wide. Loose material being blown by landing, departing, hovering, or taxiing helicopters is hazardous to both personnel and the aircraft. Rainwater running into the cracks is causing severe damage to the subgrade. Repairs are imperative to retain the useability of the airfield pavement. The use of this outlying field is necessary to meet the training requirements of Fleet Marine Force Units (Marine Aircraft Group 26) in garrison at this Activity. The formation of a Helicopter Training Group at New River, scheduled for calendar year 1969, will place a much heavier training usage on the Oak Grove airfield pavement.
232,778			
(232,778)			
0			
0			
0			
AUTHORIZED	FUNDED		
0			
PROGRAM			
78			



Activity Mech (H) NR NC Date 2/1/5 Proj Title R4-68
 Resource R/W & T/W of R4001F Code Base Line Item 1 Est Cost \$354.18
 (Include Bldg No. and Function)

1. Require Date
 - a. Overdue Deficiency (2.0)
 - b. Current Year 1.5
 - c. Projected Deficiency .5

2. Operational Influence (to mission)
 - a. Direct (2.0)
 - b. Indirect 1.5
 - c. No Effect 1.0

3. Future Damage (Rate of Deterioration)
 - a. High 3.0
 - b. Medium (2.0)
 - c. Low 1.0

4. Operational/Command Importance (Command's priority)
 - a. High 3.0
 - b. Medium 2.0
 - c. Low (1.0)

5. Cost Increase (Not Cost Escalation)
 - a. High (Over 25%) 2.0
 - b. Modest (10-25%) (1.5)
 - c. Low (Under 10%) 1.0

Computation: 2. x 2. x 2. x 1. x 1.5 = 12.0

Environmental Influence: Yes No

% of estimated cost which will contribute to environmental improvement 0

HQMC Rep Oliver Crumley Activity Rep W. G. Gault

72
24

