

6287
NREAD

OCT 02 1986

Division of Environmental Management
North Carolina Department of Natural
Resources and Community Development
7225 Wrightsville Avenue
Wilmington, North Carolina 28403

Dear Sir:

This letter is to report a 24 September 1986 bypass in the Camp Johnson (Montford Point) Wastewater Treatment System, Marine Corps Base, Camp Lejeune, North Carolina. Telephonic notification was made to your office on 24 September 1986. Approximately 3,000 gallons of wastewater were leaked into Northeast Creek when a crack developed in the terra cotta line feeding lift station M-241. The crack developed sometime after 10:00 pm (2200) on 23 September 1986 when the lift station was checked and before 9:45 am on 24 September 1986 when the leak was discovered. The bypass was stopped by 10:00 on 24 September 1986. The line was repaired and the ditch treated with 100 pounds of HTH the same day.


The wastewater went into Northeast Creek and on 24 September 1986 two samples were taken for Dissolved Oxygen (DO), Biochemical Oxygen Demand (BOD) and total coliform samples at approximately 2:00 pm (1400). Sample #1, which was upstream of the bypass had a DO of 6.9 mg/l, BOD of 5.1 mg/l and a total coliform of 7000/100 ml. Sample #2, which was downstream of the bypass, had a DO of 6.8 mg/l, BOD of 3.7 mg/l and a total coliform of 6000/100 ml.

If additional information is desired, please contact Ms. Elizabeth A. Betz, Supervisory Chemist at (919) 451-5977.

PETER BLACK
Acting Director, Natural Resources Division
Assistant Chief of Staff, Facilities
By direction of the Commanding General

Copy to:
NAVFACENCOM

Blind copy to:
NREAD
PMU
NAVHOSP
BMO
QCL (2 copies)



Memorandum

11345.4

MAIN

DATE: 25 September 1986

FROM: Utilities Systems General Foreman

TO: Director, Utilities Branch

SUBJ: NPDES PERMIT VIOLATION, M-241 LIFT STATION

1. The terra cotta line feeding lift station M-241 became cracked and a bypass occurred 24 September 1986 of approximately 3000 gallons.
2. The lift station was checked at approximately 2200, 23 September 1986 and the bypass was noted at approximately 0945 on 24 September 1986. The pumps were cut on by hand and the bypass stopped at approximately 1000, 24 September 1986.
3. The line was repaired and 100 pounds of HTH was spread in the ditch to disinfect the discharge.


W. R. PRICE

11345
MAIN
25 September 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.


G. S. JOHNSON, JR.

MEMORANDUM

DATE: 10/10/54

TO: SAC, NEW YORK

FROM: SA [Name], NEW YORK

SUBJECT: [Subject]

RE: [Subject]

The above information was obtained from [Source] on [Date].

The above information was obtained from [Source] on [Date].

Very truly yours,
[Signature]

[Handwritten initials]

U.S. GOVERNMENT PRINTING OFFICE: 1954

10-10-54

[Faint text at bottom of page]

11345.4
MAIN

25 September 1986

Utilities Systems General Foreman
Director, Utilities Branch

NPDES PERMIT VIOLATION, M-241 LIFT STATION

1. The terra cotta line feeding lift station M-241 became cracked and a bypass occurred 24 September 1986 of approximately 3000 gallons.
2. The lift station was checked at approximately 2200, 23 September 1986 and the bypass was noted at approximately 0945 on 24 September 1986. The pumps were cut on by hand and the bypass stopped at approximately 1000, 24 September 1986.
3. The line was repaired and 100 pounds of HTH was spread in the ditch to disinfect the discharge.

W. R. PRICE

11345
MAIN
25 September 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.

G. S. JOHNSON, JR.

Writer: M.D.Davis, X2069
Typist: S.H.KOLDE, 25 Sep 86

1947
1948

1949
1950

1951
1952

1953
1954

1955
1956

1957
1958

1959
1960

1961
1962

1963
1964

1965
1966


1967
1968

1969
1970

~~##~~ Wed. 24 Sep 86

	DO	DO ₁	DO ₅	PH
UP	10.4	6.9	1.8	8.3
DOWN	10.5	6.8	3.1	8.3

Camp Johnson
Sewage Line
Break



[Faint, illegible handwriting or scribbles on lined paper]

108-108

108-108
108-108
108-108

1


Memorandum

11345.4

MAIN

DID NOT GET INTO

SURFACE WATERS



1. A low sewage line at Station H-29, totaling an estimated 2000 gallons. A contract was made and it fell across the power lines, disrupting commercial power at approximately 1500. The auxiliary generator started immediately and ran for approximately 15 minutes and cut off due to low oil pressure. The gasket between the oil filter and engine block blew, causing the loss of oil. The oil filter was replaced and the generator resumed service at approximately 1545.



B. M. FRAZELLE, II
Acting

11345
MAIN
18 September 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

- 1. Forwarded for appropriate action.


G. S. JOHNSON, JR.



18 September 1964

Director, Defense Systems Research Institute

Director, Defense Research Agency

REPLY TO AIR MAIL, 14 SEP 1964

A new system program is being developed in the Defense Systems Research Institute. A contract was awarded to the Defense Research Agency for the development of a system program. The program is being developed in the Defense Systems Research Institute. The program is being developed in the Defense Systems Research Institute.

Handwritten signature or initials.

Very truly yours,

Handwritten signature or initials.

Memorandum

11345.4

MAIN

DATE: 18 September 1986

FROM: Utilities Systems General Foreman

TO: Director, Utilities Branch

SUBJ: NPDES PERMIT VIOLATION, H-29 LIFT STATION

1. A raw sewage bypass occurred on 17 Sept. 1986 at Lift Station H-29, totaling an estimated 2000 gallons. A contractor cut down a tree and it fell across the power lines, disrupting commercial power at approximately 1500. The auxiliary generator started immediately and ran for approximately 15 minutes and cut off due to low oil pressure. The gasket between the oil filter and engine block blew, causing the loss of oil. The oil filter was replaced and the generator resumed service at approximately 1545.



B. M. FRAZELLE, II
Acting

11345
MAIN
18 September 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.


G. S. JOHNSON, JR.



[Faint handwritten scribble]

[Faint handwritten scribble]

Memorandum

11345.4

MAIN

DATE: 18 September 1986

FROM: Utilities Systems General Foreman

TO: Director, Utilities Branch

SUBJ: NPDES PERMIT VIOLATION, H-29 LIFT STATION

1. A raw sewage bypass occurred on 17 Sept. 1986 at Lift Station H-29, totaling an estimated 2000 gallons. A contractor cut down a tree and it fell across the power lines, disrupting commercial power at approximately 1500. The auxiliary generator started immediately and ran for approximately 15 minutes and cut off due to low oil pressure. The gasket between the oil filter and engine block blew, causing the loss of oil. The oil filter was replaced and the generator resumed service at approximately 1545.



B. M. FRAZELLE, II
Acting

11345
MAIN
18 September 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.


G. S. JOHNSON, JR.

1950-1951
1952-1953
1954-1955
1956-1957
1958-1959
1960-1961
1962-1963
1964-1965
1966-1967
1968-1969
1970-1971
1972-1973
1974-1975
1976-1977
1978-1979
1980-1981
1982-1983
1984-1985
1986-1987
1988-1989
1990-1991
1992-1993
1994-1995
1996-1997
1998-1999
2000-2001
2002-2003
2004-2005
2006-2007
2008-2009
2010-2011
2012-2013
2014-2015
2016-2017
2018-2019
2020-2021
2022-2023
2024-2025

6287
NREAD (L)
16 Jun 86

Division of Environmental Management
North Carolina Department of Natural
Resources and Community Development
7225 Wrightsville Avenue
Wilmington, North Carolina 28403

Dear Sir:

This letter is to report a 2 June 1986 bypass in the Tarawa Terrace Wastewater Treatment System, Marine Corps Base, Camp Lejeune, North Carolina. Telephonic notification was made to your office on 2 June 1986. Approximately 7,500 gallons of wastewater overflowed from a manhole in the sewer main at the corner of Tarawa Boulevard and Peleliu Drive. This bypass was caused by a clogged sewer main at approximately 9:45 a.m. The main was cleared and the area treated with HTH by approximately 11:15 a.m.

The wastewater went into a nearby storm drain leading to Northeast Creek. The lower portion of the storm drain is tidal and had an incoming tide at approximately 1:30 p.m. when biochemical oxygen demand (BOD) and fecal coliform samples were taken. Three samples were taken on the storm drain. Sample #1 was pulled in the storm drain near its mouth into Northeast Creek and its BOD was 5.4 mg/l and fecal coliform was 1000/100 ml. Sample #3 was pulled at the upper end of the storm drain at the point where HTH had been added 2-3 hours earlier. Its BOD was 5.1 mg/l and fecal coliform was 30/100 ml. Sample #2 was half way between #1 and #3 and its BOD was 3.5 mg/l and fecal coliform was 9/100 ml.

If additional information is desired, please contact Ms. Elizabeth Betz, Supervisory Chemist at (919) 451-5977.


Sincerely,

J. I. WOOTEN
Director, Natural Resources Division
Assistant Chief of Staff, Facilities
By direction of the Commanding General

Copy to:
NAVPACENGCOM

Blind copy to:
NREA, PMU, NAVHOSP, BMO, QCL

Drafter: E. Betz, NREAD, Typist: T. Hardison, 16 Jun 86



Memorandum

DATE: 2 Jun 86

FROM: Base Maintenance Officer, Marine Corps Base, Camp Lejeune

TO: Director, Natural Resources and Environmental Affairs Division,
AC/S Facilities, Marine Corps Base, Camp Lejeune

SUBJ: SEWER SPILLAGE

1. On 2 June 1986, at approximately 0945, the sewer main at the corners of Tarawa Terrace Boulevard and Peleliu Drive spilled over. It was unstopped at about 1030, 2 June 1986 with approximately 7,500 gallons running into the creek. The creek bed was treated with HTH and the roadway cleaned up.



R. E. AVANT
By direction

MEMORANDUM

TO : [Illegible]

FROM : [Illegible]

SUBJECT : [Illegible]

[Illegible signature]

[Illegible title]

[Illegible date]

2 June 86

Sewage Bypass reported to Lab at 1010 from D. Sharpe.
from manhole in road/street at intersection of Tarawa Blvd and Peleliu Dr.


When I arrived at 1030, ^{both} utilities personnel and base maintenance personnel were on the scene. Using a high pressure water line and a "gouge" they removed the large grease deposit (household type) that was occluding the flow of sewage in the main.


Quantity of spill estimated 9,000 gallons - 10,000 gal.
100# HTH was added into the small creek. (which happens to be our storm drain #28.)

At 1120 the street had been worked, manhole cover replaced, and all personnel were gone.

Ms. Betty, Supervising Chemist called STEVE LONG to report the bypass. He directed 3 samples be taken from 3 locations in the zone of mixing for D.O., B.O.D, and fecal coliforms. I took these samples @ 1315 - 1345.

See drawing below.






NE CREEK

Sewage Bypass @ TT (Storm Drain # 28)

~~NO 1~~, ~~NO 2~~, ~~NO 3~~

SAMPLE POINT	# 1	# 2	# 3
pH	7.5	7.4	8.7
D.O.	5.4	5.7	11.0
BOD	5.4	3.5	5.1
Fecal Coliform	1000	0	30
DO ₅	0	2.2	5.9





11
10
9
8
7
6
5
4
3
2
1


QUALITY CONTROL LABORATORY REPORT
MISCELLANEOUS BACTERIOLOGICAL ANALYSIS OF WATER
 MCBCL 11330/8 (REV. 11-85)

FILE:

WATER TYPE: SURFACE SAMPLE COLLECTED BY: TAB DATE COLLECTED: 2 JUNE 86


SEWAGE BYPASS LOCATION	CL ₂	TIME	COLIFORM		
			TOTAL	FECAL	MPN
<u>NE CREEK 1</u>	<u>0</u>	<u>1330</u>	<u>0.1</u>	<u>10</u>	<u>50</u>
<u>2</u>	<u>0</u>		<u>1000</u>	<u>06</u>	<u>06</u>
<u>3</u>	<u>0</u>		<u>0</u>	<u>0</u>	<u>0</u>
				<u>30</u>	<u>06</u>

DATE	TIME	INITIALS	COLIFORM ANALYSIS BY: MF MPN
SAMPLES RECEIVED			DILUTIONS <u>0.1, 10, 50</u>
SAMPLES ANALYZED			
REMARKS			



SIGNATURE: 10. J. Burn DATE: 4 June 86

- COPY TO
- LAB/FILE
 - UTILITIES DIRECTOR
 - WATER/WASTEWATER (GENERAL FOREMAN)
 - NREAD
 - BASE PREVENTIVE MEDICINE
 - MCAS PMU




QUALITY CONTROL LABORATORY REPORT
MISCELLANEOUS BACTERIOLOGICAL ANALYSIS OF WATER
 MCBCL 11330/8 (REV. 11-85)

FILE: 11331/4

WATER TYPE: SURFACE SAMPLE COLLECTED BY: TWB DATE COLLECTED: 2 JUNE 86

SEWAGE BYPASS LOCATION		CL ₂	TIME	COLIFORM		
				TOTAL	FECAL	✓
NE CREEK	1	0	1330	1000	06	50
	2	0		0	0	0
	3	0		0	30	0.6.

	DATE	TIME	INITIALS	COLIFORM ANALYSIS BY: MF MPN
SAMPLES RECEIVED				DILUTIONS 0.1, 10, 50
SAMPLES ANALYZED				
REMARKS				




SIGNATURE: 10. J. Burn DATE: 4 June 86

- COPY TO
- LAB/FILE NREAD
 - UTILITIES DIRECTOR
 - WATER/WASTEWATER (GENERAL FOREMAN)
 - BASE PREVENTIVE MEDICINE
 - MCAS PMU

1951

1. 1000
 2. 1000
 3. 1000
 4. 1000
 5. 1000
 6. 1000
 7. 1000
 8. 1000
 9. 1000
 10. 1000

1000



X

6287


NREAD(LAB)

DIVISION OF ENVIRONMENTAL MANAGEMENT
NORTH CAROLINA DEPARTMENT OF NATURAL
RESOURCES AND COMMUNITY DEVELOPMENT
7225 WRIGHTSVILLE AVE
WILMINGTON, N.C. 28403

DEAR SIR:

THIS LETTER IS TO REPORT 2 JUNE 1986 BYPASS IN THE TARAWA
TERRACE WASTEWATER TREATMENT SYSTEM, MARINE CORPS BASE,
CAMP LEJEUNE, NORTH CAROLINA. INITIAL TELEPHONIC NOTIFICATION
WAS MADE TO YOUR OFFICE ON 2 JUNE 1986. ~~AND~~ APPROXIMATELY
7,500 GALLONS OF WASTEWATER WAS ~~DISCHARGED~~ SPILLED
FROM ~~A MANHOLE~~ ~~A~~ THE SEWER MAIN AT THE CORNERS
OF TARAWA TERRACE BOULEVARD AND PELELIU DRIVE
THROUGH A MANHOLE. THIS BYPASS WAS CAUSED ~~BY~~
WHEN THE SEWER MAIN BECAME CLOGGED, AT APPROXIMATELY
9:45 AM. ~~THE MAIN WAS CLEARED AND THE EFFECTED AREA TREATED WITH HTH~~
~~THE DRAIN HAS BEEN CLEARED.~~ BY AT APPROXIMATELY 1115

THE WASTEWATER WENT ~~TO~~ INTO A NEARBY STORM DRAIN LEADING TO
NORTHEAST CREEK. THE STORM DRAIN WAS TREATED WITH
HTH. BIOCHEMICAL OXYGEN DEMAND (BOD) AND ~~A~~ FECAL
COLIFORM SAMPLES WERE TAKEN IN THE STORM DRAIN
AT APPROXIMATELY 1:30 PM THAT AFTERNOON.




6287

NREAD(LAB)

DIVISION OF ENVIRONMENTAL MANAGEMENT
NORTH CAROLINA DEPARTMENT OF NATURAL
RESOURCES AND COMMUNITY DEVELOPMENT
7225 WRIGHTSVILLE AVE
WILMINGTON, N.C. 28403

DEAR SIR:

THIS LETTER IS TO REPORT 2 JUNE 1986 BYPASS IN THE TARAWA
TERRACE WASTEWATER TREATMENT SYSTEM, MARINE CORPS BASE,
CAMP LEJEUNE, NORTH CAROLINA. INITIAL TELEPHONIC NOTIFICATION
WAS MADE TO YOUR OFFICE ON 2 JUNE 1986. ~~AND~~ APPROXIMATELY
7,500 GALLONS OF WASTEWATER WAS ~~DISCHARGED~~ SPILLED
FROM ~~A MANHOLE~~ ~~A~~ THE SEWER MAIN AT THE CORNERS
OF TARAWA TERRACE BOULEVARD AND PELELIU DRIVE
THROUGH A MANHOLE. THIS BYPASS WAS CAUSED ~~BY~~
WHEN THE SEWER MAIN BECAME CLOGGED, AT APPROXIMATELY
9:45 AM. ~~THE MAIN WAS CLEARED AND THE EFFECTED AREA TREATED WITH HTH~~
~~THE MAIN HAS BEEN CLEARED. BY AT APPROXIMATELY 1115~~



THE WASTEWATER WENT INTO A NEARBY STORM DRAIN LEADING TO NORTHEAST CREEK. THE STORM DRAIN WAS TREATED WITH HTH. BIOCHEMICAL OXYGEN DEMAND (BOD) AND FECAL COLIFORM SAMPLES WERE TAKEN IN THE STORM DRAIN AT APPROXIMATELY 1:30 PM THAT AFTERNOON.



Handwritten scribbles or faint markings at the bottom of the page, possibly representing a signature or initials.

THE WASTEWATER WENT INTO A NEARBY STORM DRAIN LEADING TO NORTHEAST CREEK. ~~THE LOWER PORTION~~ ~~THE STORM DRAIN WAS TREATED WITH HTH~~. THE LOWER PORTION OF THE STORM DRAIN ~~IS~~ IS TIDAL AND HAD AN INCOMING TIDE AT APPROXIMATELY 1:30 PM (1330) WHEN BIOCHEMICAL OXYGEN DEMAND (BOD) AND FECAL COLIFORM SAMPLES WERE TAKEN. THREE SAMPLES WERE TAKEN IN THE STORM DRAIN. SAMPLE #1 ~~IS~~ WAS PULLED ~~IN THE STORM DRAIN~~ IN THE STORM DRAIN NEAR ~~TO~~ ITS MOUTH INTO NORTHEAST CREEK AND ITS BOD WAS 6.4 mg/L AND FECAL COLIFORM WAS 1000/100 ML. SAMPLE #3 WAS PULLED AT THE UPPER END OF THE STORM DRAIN AT THE POINT WHERE HTH HAD BEEN ADDED APPROXIMATELY 2-3 HOURS EARLIER. ITS BOD WAS 5.1 mg/L AND FECAL COLIFORM WAS 30/100 ML. SAMPLE #2 WAS ~~THE~~ HALF WAY BETWEEN #1 & #3 AND ITS BOD WAS 3.5 mg/L AND FECAL COLIFORM WAS 0/100 ML.

The wastewater went into a special storm drain leading to
Dismal Creek. The storm drain was
located with the creek. The location of the storm drain
is that and an increase of 2.5 at approximately
1:30pm (1:50) when Dismal Creek Oxygen Demand (BOD) and
Total Coliform Counts were taken. These samples
were taken in the storm drain. Sample #1 was found
in the storm drain in the storm drain area. The water in
Dismal Creek had its BOD was 0.4 mg/l and Total
Coliform was 1.0 x 10⁶ / 100 ml. Sample #2 was taken at
the upper end of the storm drain of the town. The
BOD had been roughly approximated 2.5 mg/l. The
BOD was 0.1 mg/l and Total Coliform was
1.0 x 10⁶ / 100 ml. Sample #3 was taken at
#3 and its BOD was 0.2 mg/l and Total Coliform was
1.0 x 10⁶ / 100 ml.


QUALITY CONTROL LABORATORY REPORT
MISCELLANEOUS BACTERIOLOGICAL ANALYSIS OF WATER
 MCBCL 11330/8 (REV. 11-85)

FILE:

WATER TYPE <i>SURFACE</i>	SAMPLE COLLECTED BY <i>TUB</i>	DATE COLLECTED <i>2 JUNE 86</i>
------------------------------	-----------------------------------	------------------------------------

SEWAGE BYPASS LOCATION	CL ₂	TIME	COLIFORM ✓		
			TOTAL	FECAL	
<i>NE CREEK 1</i>	<i>0</i>	<i>1330</i>	<i>0.1</i>	<i>10</i>	<i>50</i>
<i>2</i>	<i>0</i>				
<i>3</i>	<i>0</i>				


	DATE	TIME	INITIALS	COLIFORM ANALYSIS BY: MF MPN
SAMPLES RECEIVED				DILUTIONS <i>0.1, 10, 50</i>
SAMPLES ANALYZED				
REMARKS				



SIGNATURE <i>[Signature]</i>	DATE <i>4 June 86</i>
---------------------------------	--------------------------

COPY TO

<input checked="" type="checkbox"/> LAB/FILE	<input type="checkbox"/> NREAD	<input type="checkbox"/> BASE PREVENTIVE MEDICINE	<input type="checkbox"/> MCAS PMU
<input type="checkbox"/> UTILITIES DIRECTOR		<input type="checkbox"/> _____	
<input type="checkbox"/> WATER/WASTEWATER (GENERAL FOREMAN)		<input type="checkbox"/> _____	



1230, 29 May 86, Poole, Barbue

Visited ^{site of} a site break in main sewer from Midway Park
Present were 7 people from Utilities & Base Maintenance i.e.
Mr Price and Tony Snodgrass. There were 2 breaks caused by a
bulldozer grading. They had one break repaired when Sam & I
arrived. Sewage was by passing into a low area where it remained.
Snodgrass was treating the flow with HTH.
at 1315, 2nd hole was repaired. Looks like good work
Surveyor's tape was placed on the site.


From: Environmental Protection Specialist, Water Quality Control Lab

To: Supervisory Chemist, Water Quality Control Lab

Subject Report on Sewage bypass between Heavy equipment
and Brewster Blvd. on 29 May 86

1. Sam Poole and I visited the site of a break in the main
sewer that connects Midway Park with the Paradise Point area.
When we arrived there were seven people ~~the~~ present from
Utilities and Base Maintenance. Two from Utilities I recognized
were Willard Price and Tony Snodgrass. A
2. A bulldozer operator graded to close to the sewer line
and hooked the blade into the pipe and caused two
breaks ^{about 20' apart.} When we arrived, workers had completed repair
on one hole and were working on the second break.
We arrived at 1230 and by 1320 both holes were ^{water} tight.
When we left at 1400 another dozer operator had covered
the line with about 1-2 feet of dirt. Looked like a good
job. Mr L D Shepard came to inspect the repair work.
3. Tony Snodgrass added HTH to the sewage as it
flowed from the break and down the slope and collected
in a low area where it collected. Most of the sewage was
quickly absorbed by the soil. A very rough estimate would
be 1000-3000 gallons of sewage was spilled. No solids were
observed.

Tom Barbue



6287
NREAD(LAB)

19 MAR 1986

Division of Environmental Management
North Carolina Department of Natural
Resources and Community Development
7225 Wrightsville Avenue
Wilmington, North Carolina 28403

Dear Sir:

This letter is to report a 6 March 1986 bypass at Lift Station S-47A in the Hadnot Point Wastewater Treatment System, Marine Corps Base, Camp Lejeune, North Carolina. Initial telephonic notification was made to your office on 6 March 1986 and further discussed with Mr. Mike Williams on 7 March 1986. Approximately 10,000 gallons of wastewater were spilled into Wallace Creek. This bypass was caused by a malfunction of the automatic controls causing the pump to continue running. The wet well in the lift station was pumped down and air was pulled into the pump, locking it. The bypass was discovered at 1:00AM just as it started. It lasted approximately one hour while the pump was reprimed. The controls have been repaired.

As requested by your office, a Biochemical Oxygen Demand (BOD) and a Fecal Coliform sample were pulled upstream and downstream of the bypass on 7 March 1986. The upstream BOD and Fecal Coliform results were 3.4 mg/l and 60/100 ml respectively. The downstream BOD and Fecal Coliform results were 3.5 mg/l and 14/100 ml respectively.

If additional information is desired, please contact Ms. Elizabeth Betz, Supervisory Chemist at (919) 451-5977.

Sincerely,

B. W. ELSTON
Acting Assistant Chief of Staff, Facilities
By direction of the Commanding General

Copy to:
NAVFACENGCOM

Blind copy to:
DIR, PMU, NAVHOSP
BMO
→ QCL, NREAD (2)

Writer: E. Betz, NREAD 5977
Typist: J. Cross 19Mar86

1883
(1883)

ATLAS OF THE STATE OF
NEW YORK
FROM 1880 TO 1883
BY
GEO. B. WOODRUFF

Published by
GEO. B. WOODRUFF

NEW YORK: G. B. WOODRUFF, 1883.
ALBANY: G. B. WOODRUFF, 1883.
BOSTON: G. B. WOODRUFF, 1883.
PHILADELPHIA: G. B. WOODRUFF, 1883.
WASHINGTON: G. B. WOODRUFF, 1883.

Entered as second-class
July 16, 1879, at New York, N. Y.,
under No. 1053, post office
at New York, N. Y.,
acceptance for mailing at
special rate of postage
provided for in Act of
October 3, 1879, authorized
on July 16, 1879.
Approved for mailing at
special rate of postage
provided for in Act of
October 3, 1879, authorized
on July 16, 1879.

Copyright, 1883, by
GEO. B. WOODRUFF

Memorandum

11345.4
MAIN

DATE: 7 March 1986

FROM: Utilities Systems General Foreman

TO: Director, Utilities Branch

SUBJ: NPDES PERMIT VIOLATION, S-47A LIFT STATION

1. A raw sewage bypass occurred on 6 March 1986 at lift station S-47A, totaling an estimated 10,000 gallons. Malfunction of the automatic controls caused the pump to continue running. When wet well was pumped down, air was pulled into header, air locking all pumps.
2. The lift station was checked by truck route operator at 2230; everything was in order. The lift station was checked again at 0100 and found the clear well full and just starting to overflow in yard. No notice of a high level alarm was received from the maintenance duty personnel.
3. The controls were repaired, pumps primed and back in operation at 0200.

W. R. Price
W. R. PRICE

11345
MAIN
7 March 1986


FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.

G. S. Johnson, Jr.
G. S. JOHNSON, JR.

Handwritten text at the top left of the page, possibly a name or title.



11345.4
MAIN

7 March 1986

Utilities Systems General Foreman
Director, Utilities Branch

NPDES PERMIT VIOLATION, S-47A LIFT STATION

1. A raw sewage bypass occurred on 6 March 1986 at lift station S-47A, totaling an estimated 10,000 gallons. Malfunction of the automatic controls caused the pump to continue running. When wet well was pumped down, air was pulled into header, air locking all pumps.
2. The lift station was checked by truck route operator at 2230; everything was in order. The lift station was checked again at 0100 and found the clear well full and just starting to overflow in yard. No notice of a high level alarm was received from the maintenance duty personnel.
3. The controls were repaired, pumps primed and back in operation at 0200.

W. R. PRICE

11345
MAIN
7 March 1986

FIRST ENDORSEMENT

From: Director, Utilities Branch
To: Director, Natural Resources and Environmental Affairs

1. Forwarded for appropriate action.

G. S. JOHNSON, JR.


A47

→ INTO WALLACE CREEK


BY TRUCK ROUTE ABOUT 0105 JUST STARTED PUSHING
MANHOLE.

EQUIPMENT MALFUNCTION

- MAIN PUMP PUMPED GOT AIR LOCKED WOULD
RUN, WOULDN'T PUMP.
- ? HIGH LEVEL ALARMS (NO RESPONSE)
- CONTAINED BY 0900 WITH A PUMP.
- ABOUT 1 HR 150-200 GALLONS/MIN
10, -15,000 WENT OUT.
- USED ATH



BYPASS



1986

