

Discussed
w/ Fountain / 11/24/07
11/24/07

TO: SHOE

FROM: Fountain Taylor


Subject:

SHOE

Enclosed is a copy of the result of a scope discussion with the A/E. Please review AND call Fountain Taylor to discuss any items which were omitted.

Fountain Taylor

BLD	7	8C 19	✓
	43	8C 17	✓
	3B	8C 18	✓
	18	8C 13	✓



The Smith Sinnett Associates, P.A.

A R C H I T E C T S A N D P L A N N E R S

FEE PROPOSAL REVIEW

November 10, 1987

Design Branch
Public Works Dept.

Present:

Tom Wells - Smith Sinnett Associates
John Mayes - Smith Sinnett Associates
Jim Gavin - Public Works Dept.
Fountain Taylor - Public Works Dept.
John Jordan - Public Works Dept.

what about scope?

Items Discussed

BUILDING 902:

1. Remove and reinstall existing bars at windows that will have new window units installed.
2. Owner will replace all windows and doors in Arsenal portion of building. Delete this work from Architect's Scope of Work.
3. Owner estimates asbestos removal to cost \$5000.
4. Architect should survey building exterior for areas requiring tuck pointing.
5. Entire masonry veneer of building should be treated with fluid applied waterproofing.
6. Delete requirement for security glass in new exterior sliding doors and exterior windows. Use standard single pane plate glass.


BUILDING 3-B

7. Provide 8" x 8" glass insert in exterior metal door.
8. Owner recommends new vinyl siding with panel width similar to existing siding.
9. Owner estimates asbestos removal to cost \$3500.
10. Provide new solid wood interior doors in hollow metal frames.

*insulate
New interior*

BUILDING 7

11. Delete toilet partitions described in Scope of Work, (Toilets only have single water closet in each toilet).
12. Use 1-1/2" metal "Z" furring channel to furr inside of exterior walls, (typical of all buildings).
13. Provide new metal single hung windows to replace existing units.
14. Exterior sliding doors shall be replaced with hinged hollow metal doors in hollow metal frames.



BUILDING 43

15. Adequate lighting required for each cell block in PMO portion of building.
16. Owner estimates asbestos removal to cost \$3000.
17. Drawings shall require that bars on existing windows be removed to permit window replacement and reinstalled at completion of replacement.
18. Provide ramp up to new concrete landing at door into cobbler shop.
19. Make existing toilet comply with handicap requirements.


BUILDING 18

20. Owner provided schematic plan of second floor partition layout. First review submittal will incorporate layout.
21. Existing second floor head should be redesigned to provide new women's toilet with lavatory, water closet and shower.
22. Owner estimates asbestos removal to cost \$6500.
23. Provide new wood paneling only in Chief's and Secretary's offices. All other areas shall receive gypsum board.

Please call if there are any corrections required.

Respectfully,

THE SMITH SINNETT ASSOCIATES, P.A.



Tom Wells, AIA

GTW:pm

