BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
TC-1063					MCBCL 11011/3

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
4202	9/17/75	2650	paint & rpr int
4230	9/18/75	3211	Rpr & paint ext
4767	1/20/76	3509	Rpr Termite damage
1071	4/6-79	266	Install 5 new flourescent light fixtures
80-2012	1981	600.	Ext- Paint
80-C-2012	8-12-81	824.	" "
3701	10-23-81	3374	Replace ceiling diffusers
4011	8-12-83	720	Replace existing steam coil.
3744	9-3-82.	979	Replace steam coils
3964	Comp	1577	Interior paint
3883	Comp	13651	Replace window screens
4577	Comp	330	Interior paint
3029	11-18-83	381	Interior paint
3046	7-29-83	5645	Replace steam & condensate lines
3881	Comp	6479	Replace window screens
4954	10-26-84	6338	Replace roof covering
4881	Comp	1786	Interior paint
1176	3-5-82	1108	Additional mat
4386	3-19-82	47388	Renovate Bldgs
3455	9-19-88	1952	TAP WATER MAIN, INSTALL WATER LATERALS & YARD
3902	4-8-86	4319	Repl defective / deteriorated GATE VALVES
E832	1-15-86	11396	Perform Recurring Cyclic MAINT TO BLDG
3446	3-23-89	203	FABRICATE & INSTALL Sneeze Guards
4502	9-21-98	6703*	RPLC WATER HEATER - Completed by WC32 9-10-02 per Jeel RC
~~129~~ EBGO	10/28/02	714	ELEC. mech. plumb. Repr. to All RMS
EB60	8/31/01	885	01-42950 Cyclic Maint

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION