BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
1706					MCBCL 11011/3

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
AQ8-CM-126	7/12/68	396	Ext. repairs & paint
3243	5-22-74	1932	Rpr & paint ext 2 coats
5062	4-25-76	647	Repairs to doors & windows
2557	3-25-77	/	Clean up oil spill
cont.# 79-2624	FY 80	1972	Ext Paint
3903	CMP	802	Ext Repr & spot pt. before PT Contract (2)
3360	6-24-83	1750	Repr/Rpl. doors, windows & trim
3083	9-4-85	1496	Remove Asbestos.
3262	11-11-88	7625	Rplc swing type bay doors W/ Rolling doors
4458	3-12-93	8075	Misc Repairs
8337	3-26-93	1059	Install water lines & faucets
1605	10-01-93	29361	Renovate BLDG
4758		9290	Replace Bay Doors
1605	10-01-93	4543	1st Amd
1605	10-01-93	10,000	2nd Amd
4758	—	1297	Run piping for LP Gas Htrs 1st Amend
4758		4103	2nd Amd
4480	3/10/94	7433	Make Repairs to Bldg
4479	3/10/94	1119	Make Repairs to Bldg

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
1708					MCBCL 11011/3

JOB ORDER NO	DATE ~~COMPLETED~~	COST	DESCRIPTION
4104	10-16-73		Rpr leak in floor of hot well
OQN-102	9-27-67	173	Rpl conduit, wire, switches & light over hot well
4165	9/10/75	464	Rpr bldg
5255	8-2-78	3095	Requisition & replace pump for hot well
3977	2-1-78	2432	" & install repair parts for pumps
5219	7-19-78	1700	Procure contract to repair hot well
3132	1-9-79	469	Repr brick walls / Paint ext trim
3839	3-6-83	40	Caved
4078	5-30-86	780	Exterior Paint.
9035	8-25-85	755	Perform rprs. to steam condensate return System at the hot well Bldg 1708.

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION