BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
1938					

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
4239	1-26-70	285	REPAIR WATER DAMAGE
3931	10-3-69	146	REPAIRS TO BLDG
3899	10-12-70	193	PROCURE COMPRESSOR, MOTOR
5601	7/23/76	2804	ext repairs & paint
2499	11/10/76	~~2[illegible]~~ 212	install (1) hand dryer
2498	11/4/76	286	Treat for termites
5603	7/23/76	2049	ext repairs & paint
3198	10/20-78	347	Fabricate and paint (1 [illegible] 1 [illegible]
3909	3-25-80	1,243	Haul topsoil, shellrock, remove pine tree
4404	12-18-81	306	EXT. RPR Before Point Contract
4856	7-30-85	298	Rpl ceiling Door Trim; Handrail Main Elect Rpr.
3213	5-27-88	4545	Rpl Porch
8161	6-19-92	22297	CONSTRUCT NEW BLDG ON EXISTING SLAB
8161	6-19-92	13930	CHg ORIGINAL J.O. 1ST AMEND Delete 16,266 MATS
8161	6-19-92	994	2ND AMEND ADDITIONAL MATERIAL REQUIRED
8161	6-19-92	650	PROVIDE FUNDS FOR ADD'L PLUMBING MATERIAL. 3RD AMEND
8161	6-19-92	3735	ADD MATERIALS, 4th Amend

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION