

TC - Barracks

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
HQ7-230-587-260	4/28/67	574	Replace (3) motorized steam valves, (3) thermostats + (1) stop-start switch ^{in bks}
HQ7-230-587-321	8/11/66	1,893	Repair screens - doors + windows, sashes + paint new mtlbs
HQ8-CM-0NH-316	6/19/68	332	Furnish ^{install} window sashes, glass + paint
AA9-23-XX-316R6	3/14/69	520	Repair sashes, paint + glaze
4821			perform minimal repairs
4390	5-6-74	409	exter. purchase smoked glass
4575	3-29-74		minimal repairs
4374	4-9-74	5741	recurring maint to stm heating syst. in bks.
4042	2-6-74	708	elec. P.M. bks at T.C.
4358	4-12-74	708	P.M. bks in T.C. Area
4316	3-1-74	702	procure 200 windows, latches for bks.
3901	9-21-73	677	doors for CG Bks
3603	11-9-73	699	P.M. Study Elec
3606	1-7-74	5559	maint to stm heating syst.
3524	7-17-73	220	repl gutters at TC bks
3442	9-14-73	678	elec P.M. bks at TC
1002	8-10-73	844	Install flood lites
0073	7-6-73	299	Construct + install (8) bulletin boards
4805	5-21-73	1271	Procure 30 doors for TC bks
4759	5-21-73	688	" 50 screen door for TC bks
4463	4-6-73	4517	turn on + check out + repair stm, heat + elec syst.
4339	5-11-73	650	elec P.M. bks
4026	3-30-73	650	" " "
4023	3-30-73	5076	maintain stm heating
3847	10-31-72	372	purchase (24) screen doors
3674	10-6-72	648	elec PM in bks

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3590	8-2-72	648	elec P.M. in bks at T.C.
1060	10-27-72	851	Install 2" water lines w/outlets
3811	9-13-74	774	Purchase (36) screen doors & panel
3821	6-18-75	1700	Procure repair parts for Worthington
3696	12-20-74	787	PM Barrack at tent camp
3179	9-6-74	743	Elect PM Barrack
4169	3-21-75	6486	Recurring maint to heating systems
4833	2-28-75	1231	Replace steam PRV station in TC Bks
2742	3-14-75	2587	Treat for termites TC 707, 708, 709
3698	11-22-74	6486	Recurring maint to steam heating
2711	2-14-75	4311	treat for termites TC 706, 716, 717, 718, 726
4060	3-31-75	787	Elect PM for Bks at tent camp
3464	8-2-74	4607	Repair & paint stained area
3342	12-26-75	7268	Recurring maint to steam heating
4712	6-13-75	926	Replace return air grills
2628	12-19-75	1453	Treat for termites TC 749-750-751-752
1113	10-10-75	1771	Remove laundry tubs & cap lines in Bldgs
4691	7-2-76	792	Elect PM for Bks at tent camp Bldgs
4598	6-30-75	792	Elect PM Bks at tent camp Bldgs
3227	9-26-75	792	Elect PM in Bks at tent camp Bldgs
4727	5-9-75	370	Elect Repair TC 705, 706, 708, 709, 716, 717, 718, 719, 707, 728, 729, 748, 1019, 722, 726
5058	4-4-75	1589	fab 50 window dash for TC Bks
4413	9-4-81	379	correct circuit discrepancy
5190	Comp	4083	Repair roads and Ditch in C.I. area
3805	Comp	1765	Replace window screens, window screen panel

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3193	12-30-77	1056	1st Qtr Electrical PM
3198	12-31-76	8080	1st Qtr Recurring maint. to steam heating
3200	12-31-76	792	" Electrical PM
3454	10-19-77 - Cancelled	8925	2d Qtr Recurring maint to steam heating
3441	3-31-77	792	2nd Qtr Electrical PM
3455	3-31-78	1056	2nd Qtr " "
3604	7-1-77	976	3rd Qtr " "
4062	9-30-77	976	4th Qtr " "
3412	3-31-77	8080	2d Qtr Recurring Maint to steam heating
5175	-	792	4th Qtr Electrical PM
1059	11/21/76	1808	connect power to guard tower
2472	10/22/76	98	spray sound. south end
3373	10/21/76	1196	procure 50 screen door
3341	10/21/76	91	mow 8 acres
3493	11/5/76	/	Rpl fire hydrant
5392	2-16-79	469	Reinsulate duct - install sump pump
1339	9-29-78	126	Fabricate and install heavy hump and keepers unclassified material
1345	9-1-78	236	install (3) new 115 volt outlets and repair circuit to other 115 volts
1135	5-5-78	1080	Fabricate 2 doors and install doors/jambo enlarge opening floor wall
3949	3-10-78	412	check out and repair heating system in Boiler room / duct
C-81-3592	4-1-82	-	Paint int / ext
1195	Comp	1591	Install transfer switch for generator power
1196	Comp	294	shorten stem on pendant type unclassified light
1197	Comp	2349	Construct battery shop
1034	12-7-79	1676	grade / level shellrock in storage area
1101	10-5-79	4059	Install an 8" chain force around security comp

