

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4100	2-1-86	2093	Rpl 25 HP Compressor for A/C
26 2017		600	maintain intrusion alarm system
3321		1519	Repr large washing machines floor mount.
1041		4704	Relocate exhaust fan and hood
1132	4-16-91	535	FAB/INSTALL 3 WINDOW SCREENS.
3528		1420	Repr prison locks, Brig Area.
1156	5-16-91	100	CUT HOLE IN DOOR
8051	11-22-91	1563	FAB/INSTALL 12 EXPANDED METAL SECURITY SCREENS.
3746	5-8-92	14038	RPLC CHILLER FOR A/C SYSTEM.
8067	9-16-91	725	FAB/INSTALL SECURITY PANELS
3538	5-29-91	1420	RPR PRISON LOCKS IN BRIG AREA.
3746	5-08-92	14038	RPLC CHILLER
3681	3-13-92	2586	RPLC ELECT LOCKS
3811	4-9-93	593	INST ELEC OUTLETS & CABLING
8172	4-10-92	3364	INST CUT OFF VALVE
4040	5-8-92	2878	RPLC STAINLESS STEEL MIRRORS
8162	4-17-92	7918	REMOVE SUBSTANDARD WALL HALLWAY END OF MAIL ROOM
8189	6-19-92	410	FURNISH MATERIALS FOR TRP TRNG
4120	2-7-92	1872	RPLC PRISON LOCK ON SQD BAY GATE.
3342	7-17-89	16516	Rplc Emery Stand by generator
3189	11-18-88	13242	Rplc Chiller for AC system
3045	Comp	600	Maintain intrusion alarm system
4334	10/30/92	4036	Replace A/C compressor
4854	3 DEC 93	183	PROCURE ALARM TRANSMITTERS
8468	6-10-94	216	RELOCATE 2 Emer light
8497	4-1-94	647	MOUNT 2 SECURITY MIRRORS / WATCH TOWERS

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2368	2-27-86	338	INSTALL 12 Emergency Lighting Units
8814	Compl	4319	Perform recurring cyclic maint
2007	4-4-86	1210	Procure Contract For 2 Fine Supply Sys.
2209	2-22-85	422	INSTALL ADD. OUTLETS (ELECT)
2012		600	MAINT Intruder Alarm Sys (FY-86)
2043		1440	Inspect Culley Equip.
2065	9-30-85	1769	Remove Existing Disconnect & Install 100A S & Panel
2188	5-3-85	1211	INSTALL Elect Circuits For Closed Circuit TV
2261	11-22-85 Compl	604	Relocate 8 pieces of Laundry Equip. 9-9-85
2261	11-22-85	7538	Relocate 18 Pieces of Laundry Equip.
2344	11-21-86	1435	Rpl (1) Existing Water Fountain with (1) New one.
3184	Compl	2480	Rpl leaks on all institutional Plumbing Fixtures 10/25/85
3469	5-16-86	817	Rpl Plaster Recepted of Switches - Comm
3482	2-13-87	4070	Completely rebuild workshop Exhaust System
3583		1657	Dewinterize current A/C
3596	3-14-86	2510	Rpl Door & Frame, South West Hallway EXIT
5030		4,201	Perform cyclic maint.
7625		835	Paint 1st Deck
3732	2-24-86	1238	Issue mater - for self-help
4049		5497	Reph ASPHALT SURFACE & Ground in vicinity of Bldg 1041
4056	5-27-88	2021	Take up asphalt & dig Trench
✓ 4262	10-2-84	1285	RPA RIED BATH SINKS
4879	Compl	654	Paint 2nd Deck self help 6-20-85
4947	Compl	527	Replac HOT ASPHALT Shower Pan 5-23-84
5030	11-22-85	4,201	Perform cyclic maint
5602	Compl	2545	Rpl Leaky underground carbonator Regen Line.
6005	1-24-86	77	Rpl (1) window screen in scullery of mess hall
6045	10-31-85	500	Contract to Rpl (5) Cell Door - in Special Quarters