

MAIN/JLS/cmm  
4330  
4 December 1981


From: Base Maintenance Officer  
To: Public Works Officer

Subj: FY-83 Projects Program; submission of

Ref: (a) FONECON btwn J. Sellers, BMaintDiv and G. Jones, PWO on  
3 Dec 1981

VALIDATION RATING

- |     |       |      |  |
|-----|-------|------|--|
| 40  | Encl: | (1)  | Line item AS-0101, Structural Repairs, AS-504, \$133                                       |
| 19  |       | (2)  | Line item AS-0111, Replace built in wall lockers, AS-4010, \$231                           |
| 38  |       | (3)  | Line item AS-0121, Replace economizers in three boilers, AS-4151, \$90                     |
| 28  |       | (4)  | Line item 0271, Replace water filters, valves and pipe, Building 236, \$174 <sup>175</sup> |
| 28  |       | (5)  | Line item 0281, Replace water filters, valves and pipe, Building 540, \$175                |
| 28  |       | (6)  | Line item 0291, Replace water filters, valves and pipe, Building M-139, \$175              |
| 100 |       | (7)  | Line item 0301, Replace electric transformer, wire and switches, Building 1300, \$185      |
| 19  |       | (8)  | Line item 0311, Replace built in wall lockers and head partitions, Building FC-304, \$90   |
| 19  |       | (9)  | Line item 0321, Replace built in wall lockers and head partitions, Building FC-305, \$90   |
| 19  |       | (10) | Line item 0331, Replace built in wall lockers and head partitions, Building FC-306, \$90   |
| 19  |       | (11) | Line item 0341, Replace built in wall lockers and head partitions, Building FC-309, \$90   |
| 19  |       | (12) | Line item 0351, Replace built in wall lockers and head partitions, Building FC-310, \$90   |
| 19  |       | (13) | Line item 0361, Replace built in wall lockers and head partitions, Building FC-311, \$90   |
| 0   |       | (14) | Line item 0371, Replace damaged pier, BA-142 (cancelled)                                   |
| 17  |       | (15) | Line item 0381, Reroof TT Shopping Center, 11 buildings, \$191                             |
| 28  |       | (16) | Line item 0391, Replace water filters, valves and pipe, Building S-2632, \$175             |
| 45  |       | (17) | Line item 0401, Replace deaerator tank, Building M-625, \$50                               |
| 38  |       | (18) | Line item 0411, Replace burner and tube boiler number 73, Building M-625, \$130            |
| 38  |       | (19) | Line item 0421, Replace burner and tube boiler number 74, Building M-625, \$130            |
| 28  |       | (20) | Line item 0431, Replace condensate lines, Camp Johnson, \$660                              |
| 45  |       | (21) | Line item 0441, Replace UG steam and condensate lines, Camp Geiger, \$302                  |



VALIDATION  
RATING

Subj: FY-83 Projects Program; submission of

- |     |       |      |   |
|-----|-------|------|---|
| 28  | Encl: | (22) | Line item 0451, Replace digester cover, Building \$716, \$120                             |
| 28  |       | (23) | Line item 0461, Replace digester cover, Building \$717, \$120                             |
| 28  |       | (24) | Line item 0471, Replace digester cover, Building \$718, \$120                             |
| 45  |       | (25) | Line item 0481, Replace comminutor equipment in tanks 4 and 5, Building \$719, \$60       |
| 75  |       | (26) | Line item 0491, Replace boiler and digester heat coils, Building TT-35, \$60              |
| 38  |       | (27) | Line item 0501, Replace flow meters and recorders, Building RR-85, \$50                   |
| 30  |       | (28) | Line item 0511, Replace top on water reservoir, Building STT-39, \$100                    |
| 30  |       | (29) | Line item 0521, Replace water wells 612, 626 and TT-30, \$200                             |
| 30  |       | (30) | Line item 0531, Replace water softeners and filters, Building BB-190, \$185               |
| 75  |       | (31) | Line item 0541, Replace filter control valves and equipment, Building 20, \$145           |
| 42  |       | (32) | Line item 0551, Repair and repave streets in TP area, \$118                               |
| 14  |       | (33) | Line item 0561, Repair and repave parking areas, TT Shopping Center, \$190                |
| 100 |       | (34) | Line item 0571, Repair railroad track number 3, \$397                                     |
| 100 |       | (35) | Line item 0581, Repair railroad from Highway 17 to Sneads Ferry Road, \$681               |
| 100 |       | (36) | Line item 0591, Repair railroad in Industrial Area, \$174                                 |
| 100 |       | (37) | Line item 0601, Repair railroad in warehouse area, \$79                                   |
| 100 |       | (38) | Line item 0611, Repair railroad Wye to Havelock, \$1000                                   |
| 60  |       | (39) | Line item 0621, Repair number 1 and 2 precipitators, Building 1700, \$200                 |
| 80  |       | (40) | Line item 0631, Repair comminutors and channels, Building TC-563, \$52                    |
| 100 |       | (41) | Line item P0012, Replace coal feeders and pulverizers, Building 1700, \$2000              |
| 100 |       | (42) | Line item P0022, Replace casing, insulation and tile, four boilers, Building 1700, \$200. |

1. As discussed during reference (a), enclosures (1) through (42) have been previously provided for use in preparing the subject project submission. Costs indicated in enclosures (1) through (42) are shown in thousands.

R. M. DILLON  
By direction

