BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
935					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
5007	1-2-81	342	Rpl. door + window jambs, casings, window sill + Refit door
2056	2-6-81	2630	Clean up oil spill
1101	5-07-82	772	Install outlets, fixtures & heat
3260	11-30-84	476	Rpl Door casing & window casing Bldg 939
3481	12-7-87	2212	Correct Drainage + Update Outdoor Classroom Bldg 934
3220	1-11-91	432	Rem/Repl. (3) Baseboard Elec. heaters.
~~1053~~		~~1487~~	~~Install FF Safety Station~~ Jan PURGED 99

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4662	11-21-80	401	Ext + Int. repairs
3447	80	539	Repair damaged Culvert