

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4691	10-27-72	230	Fab (12) brackets for water fountains
4694	12-15-72	169	rep broken concrete steps
5482	7-23-76	214	replace broken & missing tile in Head
4828	9-2-77	—	Repair fire hydrant
5153	9-22-78	1194	Rpl ceramic tile in shower room 2 nd Deck head
1300	6-23-78	384	Construct right Blinds in Hall on each end of hall
4405	6-14-78	204	Paint portions of Bldg 1 coat as per input rept.
1318	1-12-79	133.3	make modifications to Shower Room
4580	9-02-79	489	Paint work.
1070	Comp	261	Repl panic hardware & new hardware
3704	2-6-81	84	Rpl ext doors.
3669	12-18-79	251	Remove & repl. broken or missing light diffusers
3394	12-15-80	3774	Rpl ceramic base & ceramic floor tile
3038	Comp	1500	Rpl fire exit devices in Siegel bldg.
1284	7-23-82	387	Install R-Blinds
3014	Comp	2381	Replace missing step nosing
1123	9-28-84	449	Fab. Partition with door
5825	3-6-85	621	Misc, Structural, Mech & elect rfrs
3964	CP	14,050	Fab & install bracing material to hold up sagging pipe cases ^{6 bldgs} 4-26-84
3560	CP	131	Deventize central A/C units 4-23-84
5064	6-25-85	12459	Perform cyclic maint repairs
3990	5-5-86	954	REPAIR VENETIAN Blinds
4056	5/10/92	7900	RESECURE ^{LOOSE} ALUMINUM STEPS
7159	10-01-92	15430	CYCLIC MAINT
3171	3-10-95	911	CYCLIC MAINT
3918	10/4/96	5666	CYCLIC MAINT (REF GRD G 42 FOR HARD COPY)

Purged 9-21-01

