

JOB ORDER NO	DATE COMPLETED <small>signed</small>	COST	DESCRIPTION
CONTRACT	C 7/25/68		Exterior painted
N62470-70-C-0492	12/15/70		Exterior paint
1050	10-24-69	111	Install 208V-18500 BTU A/C
4566	6-7-74	382	Repair to engine exhaust duct through out Bldg
4490	3-23-74	393	Install 500 S.F. acoustical tile on ceiling
1032	12-4-72	3257	Hook up (4) Automotive test stands
3845	7-23-71	420	Replace underground fuel tank
2684	3-5-71	368	Install Clayton engine
5075	3/29/74	1480	Paint interior
5296	5/21/74	122	clean out drain line
3650	9/24/75	13,779	Rpr & paint
2519	4/21/78	677	Install one Delta 17-300R Hydrokinetic turbo closed system engine dynamometer
2601	4-7-78	218	Remove Rpl Battery charges
2604	11-9-79	846	Remove install connect electric with + drain
4110	6-26-81	1051	Replace condensate pumping unit
1070	4-22-83	522	Install one safety station without drain
5118	5-21-82	622	Repair period to paint contract.
137	7-7-83	1937	Install exhaust system
4650	7-7-83	2300	
3020		760	Repairs to 3 Exhaust systems
1052	7-9-83	703	Fab 20 drip pans for classroom
2398	Comp.	1021	Install air, water & drain lines to HARTRIDGE Diesel Equip
1045	2-7-86	297	Remove ASBESTOS.
2091	6-27-86	660	Perform structural work to bldg.
3281	6-6-86	4295	Exterior & Interior Repairs, Replace.
8569	7-21-85	2000	CONST 2X4 STUD WALL FOR ASB GLASS DOOR

