

| JOB ORDER NO | DATE COMPLETED | COST | DESCRIPTION   |
|--------------|----------------|------|---|
| 3678         | 7-19-74        | 9/E  | Repair storm sewer  |
| 3757         | 7-26-74        | 664  | Structural meck & paint repairs   |
| 4409         | 1-5-73         | 400  | Replace door stop & paint ext   |
| 4438         | 1-16-73        | 160  | Remove & cap of old pipe under Bldg   |
| 1086         | 10-25-72       | 2733 | Modify Bldg TT-2451   |
| 7758         | 4-4-72         | 615  | Repair ceiling  |
| 7430         | 1-24-72        | 170  | Prepare & install scotch lito regn  |
| 3618         | 12-9-77        | 481  | Paint ext. of bldg. 2451  |
| 1204         | 6-10-77        | 504  | Inst. metal sec. bars on pharmacy windows <small>cut holes on wall to allow window frames</small>   |
| 0420         | 2-9-79         | 2649 | Paint interior of Bld install skilco repair all electrical outlets.   |
| F140         | 3.11.80        | 1297 | Reventurize A/C   |
| 3517         | 2-22-80        | 776  | Remove & install floor tile   |
| 4259         | 1-14-83        | 2642 | Repl. Floor Tile, Patch Sketrock, Paint Interior  |
| 4148         | 12-7-84        | 1054 | Replace Floor tile & shoe mold  |
| 3052         | 6-14-85        | 262  | Install Split Syst Heat Pump  |
| 1151         | 6-5-91         | 237  | INSTALL/CONNECT SURGICAL LIGHT / TREATMENT ROOM.  |
| 3549         | 6-5-91         | 2875 | Replc Htg & COOLING system.   |
| 8062         | 9-3-91         | 672  | REMOVE SHEET ROCK FROM WALL   |
| 1009         | 12-6-94        | 2337 | INSTALL WINDOW <small>Purged dxt</small>  |
| 3427         | 07/28/95       | 4878 | RPR Damaged <small>SEP 29 1995</small> WATER <small>SEP 29 1995</small> Break <small>SEP 29 1995</small> Materials <small>per WC 24</small> |
| Φ2Φ7         | 2/19/99        | 2657 | INSTALL DUST PROTECTION/OX <small>per customer</small>  |

