

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

TP-448

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
CM-ODG-116	5-10-68		lower flo lights to com
CM-ONB-110	3-8-67	1147	Repair ext sliding doors & windows
45174	4-21-69	108	Install switches outside on fence
1171	3-17-77	248	Remove Conduit switch & light
2597	10-24-75	0/6	Clean up oil spill
1233	3/17/76	197	install emergency shower & wash basin
5082	3/29/76	99	fabricate & install lamp guards
4748	1/19/76	101	Rpt exhaust fan
cont # 80-2011	8-25-80		Ext paint
1209	9-24-82	3008	modification and material
4057	8-26-83	1828	Replace Air Compressor unit
3101	8-19-83	5481	up grade lighting
1509	9-27-82	3008	
4851	10-22-82	16,581	Additional labor & material for shop
1047	Comp	2080	Renovate waste storage
5721	9-14-84	202	Repair Metal Bldg, Parking area
5275	3-16-84	544	Replace Transformer
3569	3-21-86	462	Install new drainage system
3316	Comp	11,484	Deliver rock to lot left to TP44P

