

BLDG NO  
BB 255

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD  
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3002	6-7-85	414	Rplc Window Screens
5773	5-17-85	1049	Rplc Str. Coil in Storage Tank
4557	5-24-85	1405	Rpr burst underground 3" copper water line
3932	7-9-85	1709	Rpr V-blinds
6034	1-10-86	528	Keprc DRAINAGE SYSTEM
3125	4-11-86	1550	Kepr MISSING VENETIAN Blinds
3756	7-11-86	704	CORRECT Erosion Problem AT Foot Bridge
3069	4-1-88	4685	Clean COILS, FAN SCROLLS, DRAIN PANS & LINES
3458	9-28-90	1771	Remove ceramic tile & reinstall so shower pan can be replaced.
4376	1-15-93	1417	Cyclic MAINT
4513	3-12-93	2536	REPAIR WATER LINE,
4513	3-12-93	460	Ammend hours w/just.
3310	6-16-95	13115	Cyclic MAINT Purged 9/29/98
3310	6-16-95	5048	Amend #1
3800	6-7-96	2624	RPR HVAC LINES / Purged 9-25-97
3800	6-7-96	749	1st And Jwr
X 4138		5520	Cyclic MAINT <sup>PURGED 99</sup> purged 9-25-97
3123	11-5-99	1991	Rplc 103 Duplex Outlets w/ GFCI
3142	11-26-99	8,290	Misc. Struct., Elec., Mech., + Plumbing Rprs to all Rms + Public Areas
103396	1-5-01	7,110	Cyclic Maint.
EBG0	6-22-01	5,506	Cyclic Maint 01-26806
EBG0	2/8/02	8,047	Cyclic Maint 02-85344
CLM1	4/15/02	5,575.00	Rpr. Shower PV 02-105319
CLM1		10,592	Prep, Prime & Paint 02-172942

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
68255 0435	10-21-77	538	Construct 2 concrete slabs - <sup>at entrance</sup> install conduit for fire
Cont. # 79-69497	12-21-81	23,633	Conversion to ventilation system
3219	10-27-79	244	Replace window sash (cancelled -)
4686	8-28-79	2231	Repair A/C compressor
4054	3-26-79	1083	Replace valve actuator
4407	6-11-79	993	Replace Mary suit hot water tank
3998	7-20-79	1049	Rprs. that have accumulated since last insp
5924	3-8-79	158	Recurring maint.
5030	8-15-80	416	Rpl. screws in shower drains cover
4547	5-8-81	2741	Rprs. to ent of lma
3302	4-3-81	474	Rpr. heating system
Q181	8-10-79	184	Rpl. air filter 1st each qtr
3061	2-19-82	1480	RPL EXT DOORS WEATHER STRIPPING
3468	1-30-81	-	RPR Heating + Cooling System
3675	9-18-81	1797	RPL Operator on Valve
3518	9-18-81	575	RPL TUBE BUNDLE IN HEAT EXCHANGER
3745	6-5-81	179	Purchase Plastic Room & Card holder sign
*5022	3-13-81	3507	Rpr balcony handrails
<del>3468</del> 3468	Comp	2952	RPR's to heating and cooling
4849	Comp	3340	Clean + Service Bathroom Fans
4824	Comp	2724	Replace window Screens Damaged or Missing
3978	11-5-82	137	Damage Report, Repair + paint Sheet Rock Wall.
3061	2-19-82	1466	Replace Weather Stripping
3806	9-24-82	846	Make Repair to Balcony Handrail
3543	8-20-82	3147	Replace "V" Blinds in Room as per list.
3133	4-22-83	1199	Replace shower pan + Bathroom Floor tile
4912	12-18-84	2767	Structural, Mech. + Elec repairs
3493	7-20-84	242	Remove + Replace damage laundry tub