

Contract 96-4842, Sampling and Analysis of Groundwater Wells, Base Wide.

1. The following water supply wells were out of service due to maintenance problems and were not scheduled:

- STC1254 ✓ ~~HP619~~
- STC1255 ✓ ~~\*RR45~~
- HP613 ✓ ~~\*RR47~~
- HP628 ✓ ~~\*RR97~~
- HP703

\*These wells are not in use and have had electrical power removed from them. Since they are sealed wells there are no provisions to gain access to purge and sample.

2. During the sampling event the following water supply wells were found to be out of commission and could not be repaired in time to be sampled:

- HP617
- HP652
- BA145
- BA190
- TC700 ✓

3. The following water supply wells were sampled from the period of 6 January - 8 January 1997.

- |                   |                   |                      |                     |          |
|-------------------|-------------------|----------------------|---------------------|----------|
| ✓646              | 650 <sup>No</sup> | 5186 <sup>No</sup>   | ✓BA164              | AS WELLS |
| ✓647              | 708 <sup>No</sup> | 607 <sup>No</sup>    | ✓AS106              | ✓AS203   |
| 705 <sup>No</sup> | 614 <sup>No</sup> | 623 <sup>No</sup>    | BB218 <sup>No</sup> | ✓AS131   |
| ✓654              | 618 <sup>No</sup> | 622                  | ✓BB44               | ✓AS190   |
| 641               | LCH4009           | ✓616                 | ✓BB47               | ✓AS191   |
| 629               | ✓LCH4007          | ✓633                 | BB221 <sup>No</sup> | ✓AS4140  |
| 621               | 704               | ✓642                 | ✓BB220              | ✓AS4150  |
| 620               | 644               | ✓606                 | ✓GSR01              | ✓AS5001  |
| 627 <sup>No</sup> | 643               | 609                  | ✓TC502              | ✓AS5009  |
| 709 <sup>No</sup> | 698 <sup>No</sup> | HP 628 <sup>No</sup> | ✓TC600              | LCH 5186 |
| 710 <sup>No</sup> | 707 <sup>No</sup> | 661                  | STC1253             |          |
| 711 <sup>No</sup> | 699 <sup>No</sup> | 662                  | TC1251              |          |
| 663               | 700 <sup>No</sup> | 640 <sup>No</sup>    | TC1256              |          |
| 706 <sup>No</sup> | 701 <sup>No</sup> | 632                  | ✓TC1001             |          |
| 648 <sup>No</sup> |                   |                      | ✓TC604              |          |
|                   |                   |                      | ✓TC1000             | #3       |

4. Recommend that the wells with the exception of RR45, RR47 & RR49, be sampled by indefinite quantity after maintenance has them repaired.

OPTIONAL FORM 99 (7-90)

FAX TRANSMITTAL

# of pages 1

To: <u>MARILYN BROWER</u>	From: <u>BILL WARD</u>
Dept./Agency: <u>EMD IL</u>	Phone #: <u>451-5783</u>
Fax #: <u>5977</u>	Fax #: <u>451-5287</u>

CLW

Contract 96-4842, Sampling and Analysis of Groundwater Wells, Base wide.

1. The following water supply wells were out of service due to maintenance problems and were not scheduled:

TC1254	TC1255	HP613	HP628	HP703
HP619	*RR45	*RR47	*RR97	

\*These wells are not in use and have had electrical power removed from them. Since they are sealed wells there are no provisions to gain access to purge and sample.

2. During the sampling event the following water supply wells were found to be out of commission and could not be repaired in time to be sampled:

HP617	HP652	BA145	BA190	TC700
-------	-------	-------	-------	-------

3. The following water supply wells were sampled from the period of 6 January - 8 January 1997.

646	650	5186	BA164	AS106
647	708	607		AS203
705	614	623	BB218	AS131
654	618	622	BB44	AS190
641		616	BB47	AS191
629	LCH4009	633	BB221	AS4140
621	LCH4007	642	BB220	AS4150
620	704		GSR01	AS5001
627	644	606	TC502	AS5009
709	643	609	TC600	
710	698	628		
711	707	661	TC1253	
663	699	662	TC1251	
706	700	640	TC1256	
648	701	632	TC1001	
			TC604	
			TC1000	

4. Recommend that the wells with the exception of RR45, RR47 & RR49, be sampled by indefinite quantity after maintenance has them repaired.

OPTIONAL FORM 99 (7-90)

**FAX TRANSMITTAL**

# of pages ▶ 1

To <i>MARILYN BROWER</i>	From <i>BILL WARD</i>
Dept./Agency <i>EMD IR</i>	Phone # <i>451-5783</i>
Fax # <i>5497</i>	Fax # <i>451-5287</i>

CLW

0000002703

9:00 1/6/97

Total of 80 wells  
but less are operational

Will start today (Monday) over 5 days

From Fixed Price

**PRE-PERFORMANCE CONFERENCE  
OIC, FSC, JACKSONVILLE, NC AREA  
MARINE CORPS ABASE, CAMP LEJEUNE, NC 28542**

**FACILITIES SUPPORT CONTRACTS  
(SERVICE CONTRACT)**

CONFERENCE DATE: 6 January 1997

**CONTRACT DATA:**

Contract Number: N62470 - 96 - D - 4842  
Contract Title: SAMPLING AND ANALYSIS OF GROUNDWATER WELLS AT THE  
MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

~~Award Amount: NTE \$12,150.00~~  
FFP Amount: \$10,800.00  
IQ Amount: NTE \$1,350.00  
Award Date: 5 Dec 1996  
Start Date: 20 Dec 1996  
Completion Date: 19 Dec 1997  
Options: Yes  
Deductions: Liquidated Damages

RR-45 } will not  
RR-47 } sample  
RR-97 }

**CONTRACTOR INFORMATION:**

Contractor: R & A Laboratories, Inc.  
Street/P.O. Box: P.O. Box 473, 106 Short Street  
City, State & Zip Code: Kernersville, NC 27284  
Telephone (home office): (910) 996-2841  
Telephone (local):  
FAX: (910) 996-0326  
President: James M. Chershire  
Supervisor/Superintendent:  
Other:  
Other:

**OIC, PERSONNEL INFORMATION:**

OIC, FSC (Contracting Officer) CDR W. J. McKerall (910) 45-2326  
FSCM (Facilities Support Contracts Manager): G. S. Johnson, Jr. (910) 45-5783  
SCM (Service Contract Manager): G. S. Johnson, Jr. (910) 45-5783  
QAE (Quality Assurance Evaluator): Bill Ward (910) 45-5783  
Supervisory Contract Specialist  
(Contracting Officer): Janice Gurganus (910) 45-5598  
Contract Specialist: (C.O.) Bobby Black (910) 45-5598  
Procurement Clerk: Rhonda Fernandez (910) 45-5598  
FAX (Contracts Office) (910) 45-5629  
FAX (FSC Office) (910) 45-5687

**DEFINITIONS:**

OIC, FSC: Officer in Charge, Facilities Support Contracts

Present  
Fire Dept  
FSC 0000002704  
Personnel  
EMD  
D + i. h. c

CLW

<u>Day 1</u>	<u>Day 2</u>	<u>Day 3</u>	<u>Day 4</u>	<u>Day 5</u>
646	650	5186	BA164	*AS106
647	708	607	BA190	*AS203
705	614	623	BB218	AS131
654	618	622	BB44	*AS190
641	617	616	BB47	*AS191
629	LCH4009	633	BB221	AS4140
621	LCH4007	642	BB220	AS4150
620	704	652	GSR01	AS5001
627	644	606	TC502	AS5009
709	643	609	TC600	
710	698	628	TC700	
711	707	661	TC1253	
663	699	662	*TC1251	
706	700	640	TC1256	
648	701	632	TC1001	
		BA145	TC604	
			TC1000	

\*High Chloride

Will not Sample

RR-45  
RR-47  
RR-97

CLW  
0000002705