



DEPARTMENT OF THE NAVY  
NAVAL HOSPITAL  
CAMP LEJEUNE, N.C. 28542

6240  
37  
IN REPLY REFER TO

15 Jan 85

From: Commanding Officer

To:

**Base Maintenance Officer, Marine Corps Base, Camp Lejeune, NC 28542**


Subj: ENVIRONMENTAL HEALTH INSPECTION RESULTS

Ref: (a) NAVMED P-5010  
(b) Base Order 6240.7

Encl: (1) Sanitation Inspection Report

1. In accordance with reference (a), an Environmental Health Inspection was performed by the Occupational and Preventive Medicine Department. Enclosure (1) notes the facility, time and date of inspection and is submitted for your information and/or appropriate action.

2. If any additional information is required, please call the Surveillance Section of Occupational and Preventive Medicine Department at extension 5707 or 2707.

  
M. P. CENTRY  
By direction

Copy to:

**Water Quality Control Lab**

CLW  
0000004510

**ENVIRONMENTAL HEALTH/SANITATION INSPECTION REPORT**

NAV HOSP (CLNC) 6240/1A (8-83)

FROM: **Commanding Officer, Naval Hospital, Camp Lejeune, NC 28542**

TO: **Base Maintenance Officer, Marine Corps Base, Camp Lejeune, NC 28542**

REF: (a) NAVMED P-5010

In accordance with reference (a) an environmental health/sanitation inspection of WATER TX. PLANT TT 38 was conducted on 11 JANES by M.T. STASH Amz. Findings and recommended corrective action are as follows.

AN \* INDICATES THAT THE FINDING HAS BEEN PREVIOUSLY REPORTED.

FINDINGS	RECOMMENDED CORRECTIVE ACTION
ETOVE AND COFFEE MESS LOCATED IN H <sub>2</sub> O ANALYSIS LAB.	
NO PROTECTIVE GEAR (GIVES & APRON) USED IN H <sub>2</sub> O ANALYSIS LAB.	
RESPIRATOR LOCATED IN H <sub>2</sub> O ANALYSIS LAB ACROSS FROM CL <sub>2</sub> ROOM WITHIN IN THE FLOW OF AIR. (IF LEAK WAS DETECTED, RESPIRATOR WOULD BE IN ACCESSIBLE.) NO EFFECTIVE RESPIRATOR PROTECTION TRAINING BEING DOCUMENTED OR DONE.	
50 LB Lime BAGS BEING STORED BY CL <sub>2</sub> INJECTION SITE AND A SMALL CHAIN IS UTILIZED TO HOLD CL <sub>2</sub> TANKS (THIS CAN BE A HAZARD IF A BAG OF LIME WAS TO FAIL AND HIT THE CL <sub>2</sub> TANKS.)	
OPERATOR NOT USING PROTECTIVE GEAR WHEN MANUALLY INJECTING LIME INTO H <sub>2</sub> O SYSTEM.	
NO EYE WASH FACILITY NOTED.	
AMMONIA BEING STORED IN ROOM NEXT TO CL <sub>2</sub> TANKS (SHOULD BE STORED OUTSIDE OF ROOM FOR CL <sub>2</sub> DETECTION.)	
<u>M. Stash Amz</u>	CLW 000000451#

2. The overall sanitary condition was found to be: Good

Copy to:  
Water Quality Control Lab

APPROVED: [Signature]  
M. P. GENTRY  
By direction